



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

A365921

Station # [REDACTED]

Station Name: [REDACTED]

Technician #: [REDACTED]

Technician Name: [REDACTED]

Signing Officer #: [REDACTED]

Signing Officer Name: [REDACTED]

Customer Details:

Name: [REDACTED]

Address: [REDACTED]

Inspection Completed Date: 04Aug2026

Inspection Expiry Date: 28Feb2027

Vehicle Details:

VIN: 1XKDDU9X34R972355

Odometer Reading: 152071 km

Year: 2004

Vehicle Make/Model: KENWORTH/HEAVY VEHICLE

Plate: [REDACTED]

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: [REDACTED]

Station Name: [REDACTED].

Technician #: [REDACTED]

Technician Name: [REDACTED]

Signing Officer #: [REDACTED]

Signing Officer Name: [REDACTED]

Customer Details:

Name: [REDACTED]

Address: [REDACTED]

Vehicle Details:

VIN: 1XKDDU9X34R972355

Odometer Reading: 152071 km

Year: 2004

Vehicle Make/Model: KENWORTH HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

		x		Air Brake System/Components (3.2)	Fixed driver side brake pot and spring and brake shoes
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	Changed out all diff airbags
		x		Drive Shaft/Universal Joints (1)	Fixed flexpipe under driveshaft
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 17 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 47.0 degrees • Brake Stroke: 1.5 in

Wheel2-On : Tire Tread Depth: 17 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 41.0 degrees • Brake Stroke: 1.5 in

Axle 2-Pass

Wheel1-On : Tire Tread Depth: 20 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 44.0 degrees • Brake Stroke: 1.5 in

Wheel2 : Tire Tread Depth: 20 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 20 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 21 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 57.0 degrees • Brake Stroke: 1.5 in

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 22 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 49.0 degrees • Brake Stroke: 1.5 in

Wheel2 : Tire Tread Depth: 20 in

Brake(1): No Brake

N/A

Wheel3 : Tire Tread Depth: 18 in

Brake(1): No Brake

N/A

Wheel4-On : Tire Tread Depth: 20 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 91.0 degrees • Brake Stroke: 1.5 in

PASS - vehicle passes inspection

Decal # A365921

Inspection Completed Date: 04Aug2026