



Vehicle Standards and Inspection

Bus Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A346386

Station #: 70249

Station Name: Redhead Equipment Ltd

Technician #: 84819

Technician Name: Jason Balabuk

Signing Officer #: 91298

Signing Officer Name: Nicole Falzetta

Customer Details:

Name:

Address:

Inspection Completed Date: 24Jun2026

Inspection Expiry Date: 30Jun2027

Vehicle Details:

VIN: 1M8TRMPAXXP060797

Odometer Reading: 1829624 km

Year: 1999

Vehicle Make/Model: MCI BUS/BUS

Plate:

Jurisdiction: Saskatchewan

Unit: 63

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Bus Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70249

Station Name: Redhead Equipment Ltd

Technician #: 84819

Technician Name: Jason Balabuk

Signing Officer #: 91298

Signing Officer Name: Nicole Falzetta

Customer Details:

Name:

Address:

Vehicle Details:

VIN: 1M8TRMPAXXP060797

Odometer Reading: 1829624 km

Year: 1999

Vehicle Make/Model: MCI BUS BUS

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
		x		Body/Bumpers (8)	RIGHT REAR BUMPER MOULDING FALLING OFF.
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
		x		Auxiliary Compartments (8)	WARNING- RIGHT SIDE COMPARTMENT DOORS DAMAGED- NOT LEVEL WITH BODY BUT SECURE.
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
		x		Exhaust/Emission System (1)	MISSING TAIL PIPE

Brake/Tire Measurements

Axle 1-Pass

Wheel1-Off : Tire Tread Depth: 14/32 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 19 mm • Brake Drum/Rotor: 43 mm

Wheel2-Off : Tire Tread Depth: 13/32 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 19 mm • Brake Drum/Rotor: 43 mm

Axle 2-Pass

Wheel1 : Tire Tread Depth: 28/32 in

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 28/32 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 19 mm • Brake Drum/Rotor: 45 mm

Wheel3-Off : Tire Tread Depth: 28/32 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 19 mm • Brake Drum/Rotor: 45 mm

Wheel4 : Tire Tread Depth: 28/32 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1-Off : Tire Tread Depth: 15/32 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 19 mm • Brake Drum/Rotor: 45 mm

Wheel2-Off : Tire Tread Depth: 14/32 in

Brake(1): Disc Brake

• Min Brake Lining/Pad: 19 mm • Brake Drum/Rotor: 45 mm

PASS - vehicle passes inspection

Decal # A346386

Inspection Completed Date: 24Jun2026

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km. Failure to do so may result in damage or serious injury.