

Jal-1

2026384



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A260168

Station #: 71369

Station Name:

Technician #: 89446

Technician Name: Kyle Kuntz

Signing Officer #: 86682

Signing Officer Name: Brad Palmer

Customer Details:

Name

Address

Inspection Completed Date: 14Nov2025

Inspection Expiry Date: 30Nov2026

Vehicle Details:

VIN: 2MN07AAM191001547

Hubometer Reading: 522708 km

Year: 2009

Vehicle Make/Model: TRAILMOBILE TRAILER/

Plate:

Jurisdiction:

Unit: 389-9606

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

15L
15L



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71369

Station Name: Warner Truck Industries Ltd.

Technician #: 89446

Technician Name: Kyle Kuntz

Signing Officer #: 86682

Signing Officer Name: Brad Palmer

Customer Details:

Name:

Address:

Vehicle Details:

VIN: 2MN07AAM191001547

Hubometer Reading: 522708 km

Year: 2009

Vehicle Make/Model: TRAILMOBILE TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
		x		Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
		x		Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 12/32 in

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 12/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Brake Drum/Rotor: 16.514 in • Brake Stroke: 1 3/4 in

Wheel3-Off : Tire Tread Depth: 12/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Brake Drum/Rotor: 16.511 in • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 12/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection	Decal # A260168	Inspection Completed Date: 14Nov2025
----------------------------------	-----------------	--------------------------------------

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km. Failure to do so may result in damage or serious injury.