



Busted Truck Service
863 Snyder Road
Moose Jaw, SK S6H 4Y4
Phone (306) 693-2204
bustedtruckservice@gmail.com
GST # 810478305

INVOICE

Date / /
Date Open 09/12/2025

Page: 1 of 3

Sold To :

Ship To :

Written By AUSTIN		Terms CASHLST		Time 11:31:26		Customer Po #		Promised		Phone		Ship Via			
Unit #		Plate #		Year 2002		Make PETE		Model 330		Kilometer/Hrs 713640/18221.0		VIN 2NPNLD9X43M803737		Engine	

Qty	Description	Price	Amount
6.000	LABOR TO REPLACE FRONT AXLE SPRING PINS SUPPLIED BY CUSTOMER		
		SubTotal	
12.000	LABOR TO REPLACE KING PINS SUPPLIED BY CUSTOMER		
		SubTotal	
3.000	LABOR TO SET INPUT BEARING ON DIFFERENTIAL		
		SubTotal	
2.000	LABOR TO DISASSEMBLE POWER DIVIDER AND INSPECT		
		SubTotal	
2.000	LABOR TO REMOVE AND INSPECT FRONT DIFFERENTIAL		
		SubTotal	
1.000	LABOR TO R&R BOTH STEER AXLE CLEVIS' AND BUSHINGS		
2.000	PRT45210129 CLEVIS BUSHING		
2.000	PRT20101010 5/8" X 5/8" CLEVIS ASSY		
		SubTotal	
.5000	LABOR TO RESECURE AIR CLEANER MOUNT STRAP		
		SubTotal	
3.500	LABOR TO REPLACE FRONT RIGHT DRIVE AXLE WHEEL SEAL		

*** ALL WHEELS MUST BE RETORQUED WITHIN 100 KM ***

I authorize the above repair work, including sublet work, to be done along with necessary materials. You and your employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle I acknowledge receipt of a copy hereof.

Parts.....
Labour.....

Shop Supplies

Thank you for your business and we look forward to serving you again.
*** ALL WHEELS MUST BE RETORQUED WITHIN 100 KM ***

Sub Total
P.s.t.....
G.s.t.....

TOTAL Continued

Paid by



Busted Truck Service
863 Snyder Road
Moose Jaw, SK S6H 4Y4
Phone (306) 693-2204
bustedtruckservice@gmail.com
GST # 810478305

INVOICE

Date / /

Date Open 09/12/2025

Page: 2 of 3

Sold To :

Ship To :

Written By AUSTIN	Terms CASHLST	Time 11:31:27	Customer Po #	Promised	Phone	Ship Via	
Unit #	Plate #	Year 2002	Make PETE	Model 330	Kilometer/Hrs 713640/18221.0	VIN 2NPNLD9X43M803737	Engine

Qty	Description	Price	Amount
2.000	PRT3828036 STEERING AXLE WHEEL SEAL		
		SubTotal	
6.000	LABOR TO R&R OUTPUT BEARINGS AND INSTALL NEW DIFFERENTIAL		
1.000	PRTDSP40P488CGL DIFFERENTIAL - REMAN		
1.000	CORPRTDSP40P488CGL Core DIFFERENTIAL - R		
-1.00	CORPRTDSP40P488CGL RETURN: Core DIFFERENTIAL - R		
2.000	PRT10462721 BEARING - CUP		
2.000	PRT10462720 BEARING - TAPERED ROLLER		
1.000	PRT127589 NUT, R PINION		
2.000	PRT3303024 HUBCAP GASKET STEMCO 3024		
1.000	PRT6489811X YOKE - ASSEMBLY END 1710		
1.000	PRTAS7001 SEAL - OUTPUT SHAFT		
3.000	PRTPPP20001 GASKET - AXLE 9 BOLT		
2.000	PRTDS657018X KIT - STRAP BEARING		
1.000	PRT127588 NUT, THRU SHAFT		
1.000	PRT51550 ANAEROB FLANGE SEALANT		
1.000	PRT3929131 WHEEL SEAL, R/R DRIVE AXLE		
17.00	PRTGEAR OIL 75W90 GEAR OIL		
		SubTotal	

*** ALL WHEELS MUST BE RETORQUED WITHIN 100 KM ***

I authorize the above repair work, including sublet work, to be done along with necessary materials. You and your employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle I acknowledge receipt of a copy hereof.

Parts.....

Labour.....

Shop Supplies

Thank you for your business and we look forward to serving you again.

*** ALL WHEELS MUST BE RETORQUED WITHIN 100 KM ***

Sub Total

P.s.t.....

G.s.t.....

Paid by

TOTAL

Continued



Busted Truck Service
863 Snyder Road
Moose Jaw, SK S6H 4Y4
Phone (306) 693-2204
bustedtruckservice@gmail.com
GST # 810478305

INVOICE

Date / /

Date Open 09/12/2025

Page: 3 of 3

Sold To :

Ship To :

Written By AUSTIN		Terms CASHLST		Time 11:31:27		Customer Po # .		Promised		Phone		Ship Via			
Unit #		Plate #		Year 2002		Make PETE		Model 330		Kilometer/Hrs 713640/18221.0		VIN 2NPPLD9X43M803737		Engine	

Qty	Description	Price	Amount
3.000	LABOR TO SHIM INPUT ON CARRIER DIFF		
		SubTotal	
1.000	LABOR TO PERFORM TRANSMISSION SERVICE		
1.000	PRT29558329 KIT - FILTER TRANSMISSION MD3060P 6"		
1.000	PRT0908959 OIL - TRANSMISSION TES668	517.94	
		SubTotal	
2.000	LABOR TO TIGHTEN FUEL TANK STRAPS		
4.000	PRTZNNM10SC16 NUT - 16MM GR10 PLATED CRS NYLK		
		SubTotal	
1.000	TRANSACTION FEE		
		SubTotal	

*** ALL WHEELS MUST BE RETORQUED WITHIN 100 KM ***

*** ALL WHEELS MUST BE RETORQUED WITHIN 100 KM ***

I authorize the above repair work, including sublet work, to be done along with necessary materials. You and your employees may operate above listed vehicle for purposes of testing, inspection or delivery at my own risk. An express Mechanic's Lien is acknowledged on above listed vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to above listed vehicle, or articles left in above listed vehicle I acknowledge receipt of a copy hereof.

Parts.....

Labour.....

Shop Supplies

Thank you for your business and we look forward to serving you again.

*** ALL WHEELS MUST BE RETORQUED WITHIN 100 KM ***

Sub Total

P.s.t.....

G.s.t.....

TOTAL

Paid by