



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A361604

Station #: 71881	Station Name: Amin Diesel Repair Ltd
Technician #: 91147	Technician Name: Osama Amin
Signing Officer #: 91146	Signing Officer Name: Brad Walker

Customer Details:

Inspection Completed Date: 27Aug2026	Inspection Expiry Date: 28Feb2027
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 1XKDP4TX0EJ967016	Odometer Reading: 900895 km
Year: 2014	Vehicle Make/Model: KENWORTH/HEAVY VEHICLE
Plate: 644NCJ	Jurisdiction: Saskatchewan
Unit: 1402	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71881	Station Name: Amin Diesel Repair Ltd
Technician #: 91147	Technician Name: Osama Amin
Signing Officer #: 91146	Signing Officer Name: Brad Walker

Customer Details:

Vehicle Details:	
VIN: 1XKDP4TX0EJ967016	Odometer Reading: 900895 km
Year: 2014	Vehicle Make/Model: KENWORTH HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
		x		Instruments/Gauges (5)	
x				Switches (7)	
		x		Brake Pedal/Actuator (3)	
		x		Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	
		x		Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
		x		Cab/Hood Safety Catches (8)	
		x		Power Steering System (4)	
		x		Fuel System (1)	
x				Battery/Wiring Condition (7)	
		x		Air Suspended Cab (8)	
x				Cab Mounts (8)	
		x		Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

		x		Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
		x		Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	
		x		Drive Shaft/Universal Joints (1)	
		x		Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 14 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 43/64 in • Cam Rotation: 65.0 degrees • Brake Stroke: 1.5 in
Wheel2-On : Tire Tread Depth: 15 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 60.0 degrees • Brake Stroke: 1.5 in

Axle 2-Pass

Wheel1-Off : Tire Tread Depth: 13 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 7/8 in • Brake Drum/Rotor: 16.5 in • Brake Stroke: 1.5 in
Wheel2 : Tire Tread Depth: 9 mm
Brake(1): No Brake
N/A
Wheel3 : Tire Tread Depth: 9 mm
Brake(1): No Brake
N/A
Wheel4-Off : Tire Tread Depth: 12 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 7/8 in • Brake Drum/Rotor: 16.5 in • Brake Stroke: 1.5 in

Axle 3-Pass

Wheel1-On : Tire Tread Depth: 16 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 50 degrees • Brake Stroke: 1.5 in
Wheel2 : Tire Tread Depth: 16 mm
Brake(1): No Brake
N/A
Wheel3 : Tire Tread Depth: 22 mm
Brake(1): No Brake
N/A
Wheel4-Off : Tire Tread Depth: 12 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 7/8 in • Brake Drum/Rotor: 16.5 in • Brake Stroke: 1.5 in

Axle 4-Pass

Wheel1-On : Tire Tread Depth: 15 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 60.0 degrees • Brake Stroke: 1.5 in
Wheel2 : Tire Tread Depth: 16 mm
Brake(1): No Brake
N/A
Wheel3 : Tire Tread Depth: 15 mm
Brake(1): No Brake
N/A
Wheel4-On : Tire Tread Depth: 13 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 60.0 degrees • Brake Stroke: 1.5 in

PASS - vehicle passes inspection	Decal # A361604	Inspection Completed Date: 27Aug2026
----------------------------------	-----------------	--------------------------------------

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km.
Failure to do so may result in damage or serious injury.