



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A286898

Station #: [REDACTED]

Technician #: [REDACTED]

Signing Officer #: [REDACTED]

Customer Details:

Name: [REDACTED]

Address: [REDACTED]

Inspection Completed Date: 26Oct2026

Inspection Expiry Date: 31Oct2027

Vehicle Details:

VIN: 2M9GT3450JW189347

Hubometer Reading:

Year: 2018

Vehicle Make/Model: BERG/TRAILER

Plate: 857 KUX

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: [REDACTED]

Technician #: [REDACTED]

Signing Officer #: [REDACTED]

Customer Details:

Name: [REDACTED]

Address: [REDACTED]

Vehicle Details:

VIN: 2M9GT3450JW189347

Hubometer Reading:

Year: 2018

Vehicle Make/Model: BERG TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
X				Vehicle Identification (5)	
X				Fire Extinguisher (5)	
X				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
X				Lamps (6)	
X				Reflex Reflectors (6)	
X				Retro Reflective Markings (6)	
X				Trailer Hitch (10)	
X				Attached Equipment (8)	
X				Cargo Bodies/Vessels (8)	
X				Mud Flaps/Fenders (8)	
X				Landing Gear (8)	
X				Rear Impact Guard (8)	
X				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
X				Fuel System (1)	
X				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	BRAKE POT PUSH ROD TOO SHORT. LHC CLEVIS PIN ROTTED OFF. ABS WIRES CENTER AXLE NEED TIED SECURED. STICKY S-CAMS ON CENTER AXLE. RHF PAWL SEIZED. SEIZED CLEVIS PINS. REAR DOT CRACKED WELDS. ADJUST PUSHROD. REMOVE & REPLACE ROTTED CLEVIS PIN. TIE UP ABS LINES. GREASE S-CAMS. REPLACE PAWL. UNSEIZE CLEVIS PINS. WELD CRACKS.
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 11/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 11/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 41.0 degrees • Brake Stroke: 1 in

Wheel3-On : Tire Tread Depth: 7/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 42.0 degrees • Brake Stroke: 1 in

Wheel4 : Tire Tread Depth: 11/32 in

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 17/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 16/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 95.0 degrees • Brake Stroke: 1 in

Wheel3-On : Tire Tread Depth: 18/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 96.0 degrees • Brake Stroke: 1 in

Wheel4 : Tire Tread Depth: 16/32 in
Brake(1): No Brake
N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 15/32 in
Brake(1): No Brake
N/A

Wheel2-On : Tire Tread Depth: 15/32 in
Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 76.0 degrees • Brake Stroke: 1 in

Wheel3-On : Tire Tread Depth: 12/32 in
Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 77.0 degrees • Brake Stroke: 1 in

Wheel4 : Tire Tread Depth: 15/32 in
Brake(1): No Brake
N/A

PASS - vehicle passes inspection

Decal # A286898

Inspection Completed Date: 26Oct2026