



### TANK WASH AND PURGE TEST

Date: 3/5/2026 Time: 10:58 AM

Location: DE TANK WASH

Tank Unit# 14233

Meter Used: 215933

Reading:  
% LEL Level: 0 %O2: 20.8 CO: 0 H2S: 0

Tested Clean? Y/N

Comments: I metered this unit, levels look good.

Printed Name: David Richard

Signature\*: [Signature]

\*this signature verifies that this tanker has been washed out and purged

Title: Supervisor

Contact Phone Number: 281-910-1115