

Print Report



Experian AutoCheck Report

Report run: 06/17/2026 11:32:23 EDT

2019 Volvo VNL
Semi-Trailer Truck 2D (12.8L I6 DI Diesel)

VIN:	4V4NC9EH6KN903800
Class:	Medium/Heavy Truck
Country of Assembly:	United States
Estimated In Service:	03/21/2018
Last Reported Odometer:	50 (06/08/2018)

[View Vehicle Label](#)

Owners - 2



Vehicle Usage
Lease

AutoCheck Score

AutoCheck Score Not Available

Vehicle History at a Glance



State
Title
Brand



Clean






No Issue





Minor





No Open Recalls





No Issue






No Issue





No CPO Info Available





No Issue





Events Reported



This vehicle is not eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

Learn More

Accident & Damage [Back To Top](#)



Damage Date	Damage Type	Severity
06/04/2020	Collision	Minor

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.



Airbag Deployed



Structural Damage



Overturned



Minor

Odometer Check [Back To Top](#)

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check
No issues reported



Auction Odometer Check
No issues reported



Odometer Calculation Check
No issues reported

Detailed Vehicle History [Back To Top](#)

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2019 Volvo VNL (4V4NC9EH6KN903800) **Report Run Date:** 06/17/2026 11:32:23 EDT

2018

[Owner 1](#)

Location: IN

Owned From: 03/2018

Usage: Lease

Event Date - 03/21/2018

Location - IN

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal(Leased Vehicle)
Pro-Rated Registration

Event Date - 06/08/2018

Location - PHOENIX, AZ

Odometer - 50

Data Source - Motor Vehicle Dept.

Details - Title(Title #:023L018159015) (Leased Vehicle)

Event Date - 08/01/2018

Location - IN

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal(Leased Vehicle)

Pro-Rated Registration

Event Date - 08/01/2019

Location - IN

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Pro-Rated Registration

Event Date - 06/04/2020

Location - CO

Data Source - State Agency

Details - Collision with Another Vehicle(Case #:4C201342)

Accident Reported(Report #:4C201342)

Minor Damage Reported

Event Date - 08/01/2020

Location - IN

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal

Pro-Rated Registration

Event Date - 04/07/2021

Location - BLOOMINGDALE, IL

Data Source - Motor Vehicle Dept.

Details - Title(Title #:210977039140) (Lien Reported)

Excluded/Exempt

2021

[Owner 2](#)

Location: IL

Owned From: 04/2021

Usage: Personal

Event Date - 04/28/2021

Location - BLOOMINGDALE, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal
Pro-Rated Registration

Event Date - 03/03/2022

Location - BLOOMINGDALE, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal
Pro-Rated Registration

Event Date - 03/27/2023

Location - BLOOMINGDALE, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal
Pro-Rated Registration

Event Date - 04/01/2024

Location - WOODSTOCK, IL

Data Source - Motor Vehicle Dept.

Details - Registration Event/Renewal
Pro-Rated Registration

This Vehicle's Glossary [Back To Top](#)

More information is available in the full [AutoCheck glossary](#).

Term - State Title Brand

Section Location - Vehicle History at a Glance

Definition - A "branded title" is an official designation assigned by a state agency to associate a particular history with a vehicle. The branding system was put in place to warn potential owners about damage or other alterations to a vehicle that they might otherwise have been unaware of. The brands checked in this section are Fire, Hail, Flood, Junk/Scrapped, Lemon, Salvage, Rebuilt/Rebuildable, Odometer Brands (not actual miles, broken odometer, exceeding mechanical limits, mileage discrepancy, or suspect miles). Please note Grey Market and Insurance Loss or Theft brands are not checked in this box and can be found on other corresponding boxes.

Term - Auction Issue

Section Location - Vehicle History at a Glance

Definition - This section summarizes any issues if reported such as damage condition from seller's disclosure or during the inspection process including required structural damage disclosure, title brands, odometer issues, etc. as outlined by the [National Auction Automotive Association Arbitration Policy 2025](#).

Term - Accident/Damage Check

Section Location - Vehicle History at a Glance

Definition - This section summarizes vehicle history events that may indicate an accident or damage and associated details such as point of impact, severity or airbag deployed if provided. These damage events will include collision damage information, police-reported accidents, salvage auction, recycler records, crash test vehicles, collision damage claims etc. including our exclusive auction announcements from two major auctions that may include damage events. There is also a clearly delineated section that includes non-collision damage events such as fire, hail or flood. Damage-indicated title brands will be in the state title brands section.

Term - Insurance Loss/Title Transfer

Section Location - Vehicle History at a Glance

Definition - This box checked to see if there is an insurance total loss or if a title has been transferred to an insurance company name as that event usually signifies that it is a total loss when showing after an accident.

Term - Additional History

Section Location - Vehicle History at a Glance

Definition - This section lists any other significant events that may not be a damage event or brand, but does give additional insights of the vehicle's history. These include abandoned, grey market, lien check, repossessed, theft etc.

Term - Odometer Check

Section Location - Vehicle History at a Glance

Definition - This section verifies if there are rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

Term - Loan/Lien

Section Location - Additional History

Definition - A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.

Term - Lease Use

Section Location - Owner Type

Definition - Vehicle was registered as lease vehicle.

Term - Accident

Section Location - Accident / Damage

Definition - A state or municipality has reported an accident or collision for this vehicle that may or may not have sustained damage. Not all damage events are reported to AutoCheck and the damage severity of reported events will vary. In all events AutoCheck recommends that prospective vehicle purchasers conduct a detailed vehicle inspection prior to purchase of a pre-owned vehicle.

Term - Excluded / Exempt

Section Location - Odometer Check

Definition - Vehicle is generally exempt from normal/mandatory odometer law for the following reasons:

1. Vehicle model year is 10 years or older
2. Gross weight of vehicle over 16000 lbs
3. Vehicle is not self-propelled
4. Titled to the manufacturer

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (4V4NC9EH6KN903800) does not qualify for AutoCheck Buyback Protection.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.