



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

560M SHF TRD(484562)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		*REPRINT*
Date	Time	Page
10/01/24	23:08:42 (B)	01
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W01288
Ship Via		Purchase Order
		Salesperson
		JAF

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
030257	560M SUNDERLAND	11230	1E0560MDVMN484562	06/02/23	
	560M				

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 9753 NA 09/11/24 09/11/24

TOP ROLLER BEARING CAUGHT ON FIRE

NOTE:

TOM SCRIBER IS ON HIS WAY IN NOW.

***** TECHNICIANS COMMENTS *****

*
*+open rear tailgate
*+lock valve
*+put tension arm down to get access to tension roller
*+remove bolts
*+remove roller
*+put in vice remove shaft found shaft to be damaged
*+and roller to be damaged
*+installed new shaft into new roller
*+greased bearings and installed dust caps
*+installed roller and tightened bolts to spec
*+ran baler and checked all other bearings
*+all bearings seem to check out ok
*

AE46819	ROLLER SHAFT	1	887.25	887.25
AE52191	ROLLER 59.5"	1	1406.96	1406.96
	PARTS		2294.21	
	LABOR		550.80	

CONTINUED ON PAGE 02

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Lloydminster
Box 10039 • Lloydminster, AB T9V 3A2
Tel: 780.875.4471 Fax: 780.875.6606
www.horizonagturf.com

Ship to:

560M SHF TRD(484562)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 10/01/24	Time 23:08:42 (B)	Page 02
Account No. INTER01A	Phone No. 7808754471	Invoice No. W01288
Ship Via		Purchase Order
		Salesperson JAF

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
030257	560M SUNDERLAND	11230	1E0560MDVMN484562	06/02/23	
	560M				
	16001001			SEGMENT TOTAL==>	2845.01

SEGMENT# 2 C 9753 NA 09/11/24 09/11/24

INSTALL NETWRAP GUIDE KIT

***** TECHNICIANS COMMENTS *****

*

*

*+installed net guide kit

*

*

*

AFH223103	Chain Link	6	3.47	20.82
FH345025	NET GUIDE	3 S	21.82	65.46
			PARTS	86.28
			LABOR	90.00
	16001001		SEGMENT TOTAL==>	176.28

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
--	----------	----------

PARTS	2380.49	
-------	---------	--

LABOR	640.80	
-------	--------	--

Shop Supplies	64.08	
---------------	-------	--

INTERNAL TOTAL	3085.37	
----------------	---------	--

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

560M SHF TRD(484562)

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch		
LLOYDMINSTER		*REPRINT*
Date	Time	Page
03/18/24	23:30:18 (B)	01
Account No	Phone No	Inv No
INTER01	7808754471	S80538
Ship Via		Purchase Order
		Salesperson
		JAF

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
030257	560M SUNDERLAND 560M	522	1E0560MDVMN484562	06/02/23		

SEGMENT# 1 C 730 NA 01/31/24 01/09/24 03/18/24 3.91 HRS

BALER MAKES SOFT BALES

BALER WAS ON DEMO & WOULD NOT MAKE FIRM BALES - DIAGNOSE &
REPAIR- REPEAT PROBLEM WITH THIS BALER

***** TECHNICIANS COMMENTS *****

*
*+active soft core was not engaged in monitor, engaged it
*+as per instructions
*+deactivate variable core through proper channel
*+variable core is for starting bales where material is hard
*+and hard to start a bale variable core is only used on
*+machines where customers do a variety of baling different
*+crops and used for different bale densitys and weights
*

AFH206066	SENSOR	1	149.98	149.98
			PARTS	149.98
			LABOR	672.52
16002		SEGMENT TOTAL==>		822.50

******* WORK ORDER TOTALS *******

	INTERNAL	CUSTOMER
PARTS	149.98	
LABOR	672.52	
SHOP SUPPLIES	47.07	
INTERNAL TOTAL	869.57	

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X
Signature

Date

Solutions from the Ground Up



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

560M SHF TRD(484562)

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER *REPRINT*		
Date 10/05/23	Time 23:30:35 (B)	Page 01
Account No INTER01	Phone No 7808754471	Inv No S78745
Ship Via		Purchase Order
		Salesperson JAF

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
030257	560M SUNDERLAND 560M		X 1E0560MDVMN484562	06/02/23		

SEGMENT# 1 C 745 NA 09/25/23 09/25/23

REPAIR OR REPLACE DAMAGED TEETH AND STRIPPERS
(AS PER JOHN) - CONFIRM WITH ARRON

***** TECHNICIANS COMMENTS *****

*
*+replaced 29 pickup teeth and 4 RHS mega teeth
*+rotor teeth look to be in good shape
*+strippers are still in good condition
*

E90880	TOOTH RH MEGA	4	19.07	76.28
FH304454	WASHER	22	1.79	39.38
FH304576	SPRING TOOTH	29	12.13	351.77
FH323638	WASHER	4	3.99	15.96
M82222	LOCK NUT M10	26	2.38	61.88
19M7804	M10X40 FL/BOLT	4	3.02	12.08
19M8533	M10X25MM ALLEN	22	3.16	69.52
	PARTS			626.87
	LABOR			818.83
16002	SEGMENT TOTAL==>			1445.70

SEGMENT# 2 C 745 NA 09/25/23 09/25/23

DIAGNOSE AND REPAIR OIL LEAK

***** TECHNICIANS COMMENTS *****

*
*+a fitting on valve block was loose
*+replaced o ring & tightened fitting
*

CONTINUED ON PAGE 02

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X
Signature

Date

Solutions from the Ground Up



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

560M SHF TRD(484562)

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 10/05/23	Time 23:30:35 (B)	Page 02
Account No INTER01	Phone No 7808754471	Inv No S78745
Ship Via		Purchase Order
		Salesperson JAF

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
030257	560M SUNDERLAND		X 1E0560MDVMN484562	06/02/23		
	560M					
R26906		O-RING #10	1	5.33	5.33	
				PARTS	5.33	
				LABOR	192.53	
	16002		SEGMENT TOTAL==>		197.86	

SEGMENT# 3 C 745 NA 09/25/23 09/26/23
RUN BALER AND DO QUICK WALK AROUND BEFORE IT GOES ON DEMO
***** TECHNICIANS COMMENTS *****
*
*+ran baler & check operation
*+shim gate latch LHS and RHS
*+greased baler
*+added 1L of oil to auto luber
*+tightened rotor blade plastic shims between rotor teeth
*

TY22029	10w30 TURF-GARD	1	8.51	8.51
			PARTS	8.51
			LABOR	374.64
	16002	SEGMENT TOTAL==>		383.15

	***** WORK ORDER TOTALS *****
	INTERNAL CUSTOMER
PARTS	640.71
LABOR	1386.00
SHOP SUPPLIES	97.02
INTERNAL TOTAL	2123.73

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X
Signature

Date

Solutions from the Ground Up



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

560M SHF TRD(484562)

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER			*REPRINT*		
Date 08/08/23	Time 23:30:22 (B)		Page 01		
Account No INTER01	Phone No 7808754471		Inv No S74422		
Ship Via		Purchase Order			
		Salesperson JAF			

DESCRIPTION OF WORK & PARTS

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
030257	560M SUNDERLAND 560M	X 1E0560MDVMN484562	06/02/23		

SEGMENT# 1 C 730 10-000-300 05/22/23 06/19/23

TRADE UNIT - PERFORM TRADE INSPECTION 5.00 HRS

-ADVISE OF BALER CONDITION -REMOVE OUTER 2 HOOPS FORINSPECTN

-TOUCH UP PAINT ON PICKUP AND OTHER NECESSARY AREAS

-ADVISE OF SAFETY SHIELDS OR DECALS NOT IN PLACE

-PLACE MONITOR IN BOX,MARK CUSTOMER NAME ON BOX & PUT IN

PROPER LOCATION IN SET-UP SHOP

-PUT OPERATORS MANUAL IN BOX

-GREASE MACHINE COMPLETE AND CHECK AND ADJUST TIRE PRESSURES

CHAIN LUBE ALL CHAINS AFTER RUNNING -- KEEPS FROM RUSTING

BEFORE PARKING IN FRONT LINE, HAVE SERVICE AND SALES MGMT

PERSONNEL DOUBLE CHECK EQUIP TO ENSURE READY FOR RESALE.

ENSURE AGLAND DECALS ARE IN PLACE.

-RUN BALER TO CHECK OPERATION-HOOK UP MONITOR AND CYCLE

THROUGH TWINE CYCLE- CHECK ALL SWITCHES AND LIGHTS ON

MONITOR

***** TECHNICIANS COMMENTS *****

*

*+perform trade inspection

*

	LABOR	840.00
16002	SEGMENT TOTAL==>	840.00

SEGMENT# 2 C 730 NA 02/17/23

WASH AS NEEDED

***** TECHNICIANS COMMENTS *****

*

*+wash bay to do

CONTINUED ON PAGE 02

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X
Signature

Date

Solutions from the Ground Up



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

560M SHF TRD(484562)

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 08/08/23	Time 23:30:22 (B)	Page 02
Account No INTER01	Phone No 7808754471	Inv No S74422
Ship Via		Purchase Order
		Salesperson JAF

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
030257	560M SUNDERLAND 560M		X 1E0560MDVMN484562	06/02/23		Fold

* *

SEGMENT# 4 C 730 NA	06/20/23 06/22/23			
FAILED PART: BE32688	FAILED TYPE (3)		.95 HRS	
CONSTANT VELOCITY U-JOINT IS FAILED - DIAGNOSE & REPAIR				
***** TECHNICIANS COMMENTS *****				
* *				
*+found CV joint cracked				
*+replaced drive shaft				
* *				

BE32688	CAT5 1-3/81000	1	2897.83	2897.83
			PARTS	2897.83
			LABOR	159.60
10500 16002		SEGMENT TOTAL==>		3057.43

SEGMENT# 6 C 730 NA	06/20/23 06/22/23			
FAILED PART: R64987	FAILED TYPE (3)		1.07 HRS	
OVERSIZE SWITCH LINKAGE ARM SPRING IS BROKE - DIAGNOSE & REPAIR				
***** TECHNICIANS COMMENTS *****				
* *				
*+found spring is broke - weak material				
*+replace oversize switch return spring				
* *				

R64987	SPRING	1	12.75	12.75
			PARTS	12.75
			LABOR	179.76
CONTINUED ON PAGE 03				


- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X

Signature

Date

Solutions from the Ground Up



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

560M SHF TRD(484562)

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 08/08/23	Time 23:30:22 (B)	Page 03
Account No INTER01	Phone No 7808754471	Inv No S74422
Ship Via		Purchase Order
		Salesperson JAF

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
030257	560M SUNDERLAND		X 1E0560MDVMN484562	06/02/23		
	560M					
	10500			SEGMENT TOTAL==>	192.51	

SEGMENT# 7 C 730 NA	06/20/23 06/22/23			
FAILED PART: AW25863	FAILED TYPE (14)	2.07 HRS		
MAIN GEARBOX IS LEAKING - DIAGNOSE & REPAIR				
***** TECHNICIANS COMMENTS *****				
*	*			
*+washed oil residue & ran baler	*			
*+front input seal leaking	*			
*+replaced seal	*			
*	*			

AW25863	SEAL	1	62.85	62.85
			PARTS	62.85
			LABOR	347.76
10500		SEGMENT TOTAL==>		410.61

SEGMENT# 8 C 730 NA	06/20/23 06/22/23			
FAILED PART: AE11579	FAILED TYPE (6)	.98 HRS		
BALE SHAPE IDLER BEARINGS ARE FAILED - DIAGNOSE & REPAIR				
***** TECHNICIANS COMMENTS *****				
*	*			
*+bearings are dry and have excessive play	*			
*+replaced bale shape idler bearings	*			
*+replaced idler bearings	*			
*	*			

AE11579	BEARING	2	29.99	59.98
			PARTS	59.98
			LABOR	164.64
CONTINUED ON PAGE 04				

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X

Signature

Date

Solutions from the Ground Up



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

560M SHF TRD(484562)

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 08/08/23	Time 23:30:22 (B)	Page 04
Account No INTER01	Phone No 7808754471	Inv No S74422
Ship Via		Purchase Order
		Salesperson JAF

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
030257	560M SUNDERLAND		X 1E0560MDVMN484562	06/02/23		
	560M					
	10500			SEGMENT TOTAL==>	224.62	

SEGMENT# 9 C 730 NA	06/20/23 06/22/23			
FAILED PART: 03M7196	FAILED TYPE (6)	2.00 HRS		
NET PAN MISSING SHIMS & HARDWARE IS LOOSE - DIAGNOSE & REPAIR				
***** TECHNICIANS COMMENTS *****				
* * *				
*+found hardware came loose & felt out				
*+install new hardware and shims				
* * *				

E97978	SHIM	6	7.70	46.20
03M7196	BOLT-M10X50MM	2	3.79	7.58
14M7296	NUT-10MM FLG HD	2	1.85	3.70
14M7400	NUT-10MM LOCK	2	2.14	4.28
24H1307	WASHER	6	1.01	6.06
	PARTS			67.82
	LABOR			336.00
10500	SEGMENT TOTAL==>			403.82

SEGMENT#10 C 730 NA	06/20/23 06/22/23			
FAILED PART: AM127325	FAILED TYPE (6)	.63 HRS		
LHS GAUGE WHEEL BEARING FAILED - DIAGNOSE & REPAIR				
***** TECHNICIANS COMMENTS *****				
* * *				
*+found bearing has excessive play				
*+replaced gauge wheel bearing				
* * *				

CONTINUED ON PAGE 05

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X
Signature

Date

Solutions from the Ground Up



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

560M SHF TRD(484562)

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 08/08/23	Time 23:30:22 (B)	Page 05
Account No INTER01	Phone No 7808754471	Inv No S74422
Ship Via		Purchase Order
		Salesperson JAF

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
030257	560M SUNDERLAND 560M		X 1E0560MDVMN484562	06/02/23		
AM127325		BALL BEARING	2	34.64	69.28	
				PARTS	69.28	
				LABOR	113.57	
10500			SEGMENT TOTAL==>		182.85	

SEGMENT#11 C 730 NA 06/26/23 07/04/23
NET BRUSH NEEDS TO BE BLOWN OUT AND ADJUSTED 2.50 HRS
STATIONARY KNIFE NEEDS TO BE ADJUSTED SO THREE POINTS OF
CONTACT WITH COUNTER KNIFE
NET BRAKE NEEDS TO HAVE FULL ADJUSTMENT DONE
***** TECHNICIANS COMMENTS *****
*
*+removed brush and cleaned it out
*+adjust counter knife
*+adjusted brake
*

LABOR 420.00
16002 SEGMENT TOTAL==> 420.00

SEGMENT#12 C 730 NA 06/26/23 07/04/23
SPIRAL BAND ROLLER HAS NICKS & BURRS - REPAIR 1.00 HRS
***** TECHNICIANS COMMENTS *****
*
*+buffed out nicks and burs
*

LABOR 168.00
16002 SEGMENT TOTAL==> 168.00

CONTINUED ON PAGE 06

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X
Signature

Date

Solutions from the Ground Up



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

560M SHF TRD(484562)

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 08/08/23	Time 23:30:22 (B)	Page 06
Account No INTER01	Phone No 7808754471	Inv No S74422
Ship Via		Purchase Order
		Salesperson JAF

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
030257	560M SUNDERLAND		X 1E0560MDVMN484562	06/02/23		
	560M					

SEGMENT#13 C 730 NA 06/26/23 06/26/23
CHAIN OILER RESERVOIR IS EMPTY NEEDS TO BE FILLED AND LINES .50 HRS
PURGED WITH OIL

***** TECHNICIANS COMMENTS *****

* *

*+topped up reservoir & bled *

* *

TY22029	10w30 TURF-GARD	2	8.64	17.28
			PARTS	17.28
			LABOR	84.00
16002	SEGMENT TOTAL==>			101.28

SEGMENT#14 C 730 NA 06/26/23 06/26/23
DOUBLE DRIVE SPROCKET IS WORN - REPLACE 6.00 HRS
ALL CHAINS ARE WORN OUT - REPLACE

***** TECHNICIANS COMMENTS *****

* *

*+replaced sprocket, replaced chains and tightened to spec *

* *

AFH206114	DIAMND #80 158L	1	585.17	585.17
AFH206115	DIAMND #80 64L	1	257.46	257.46
AFH207881	Chain Sprocket	1	296.36	296.36
AFH208831	DIAMND 60H 42L	1 O	96.91	96.91
SW50COUS	#50 CONN. LINK	1	4.72	4.72
SW50X10US	#50 CHAIN	1	168.78	168.78
			PARTS	1409.40
			LABOR	1008.00
16002	SEGMENT TOTAL==>			2417.40

CONTINUED ON PAGE 07

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X
Signature

Date

Solutions from the Ground Up



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

560M SHF TRD(484562)

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 08/08/23	Time 23:30:22 (B)	Page 07
Account No INTER01	Phone No 7808754471	Inv No S74422
Ship Via		Purchase Order
		Salesperson JAF

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
030257	560M SUNDERLAND 560M		X 1E0560MDVMN484562	06/02/23		

SEGMENT#15 C 730 NA	06/26/23 06/26/23				
ALL BELT PINS NEED TO BE REPLACED		1.00	HRS		
***** TECHNICIANS COMMENTS *****					
*+replaced all belt pins					
E86147	MATO PIN-6"	8	7.28	58.24	
			PARTS	58.24	
			LABOR	168.00	
16002	SEGMENT TOTAL==>			226.24	

SEGMENT#16 C 730 NA	06/26/23 07/04/23				
NET WRAPPED ON #11 ROLLER - REMOVE		1.15	HRS		
***** TECHNICIANS COMMENTS *****					
*+removed net wrap from roller					
			LABOR	193.20	
16002	SEGMENT TOTAL==>			193.20	

SEGMENT#17 C 730 NA	06/26/23 06/26/23				
DAMAGE - 3 PICKUP TEETH BROKE - REPLACE		1.50	HRS		
2 MIDDLE BANDS ON PICKUP ARE WORN - REPLACE					
1 OUTER BAND ON RHS OUTER IS WORN - REPLACE					
***** TECHNICIANS COMMENTS *****					
*+replaced three fingers and three bands					

CONTINUED ON PAGE 08

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X
Signature

Date

Solutions from the Ground Up



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

560M SHF TRD(484562)

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 08/08/23	Time 23:30:22 (B)	Page 08
Account No INTER01	Phone No 7808754471	Inv No S74422
Ship Via		Purchase Order
		Salesperson JAF

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
030257	560M SUNDERLAND	X	1E0560MDVMN484562	06/02/23		
	560M					

*		*

FH304454	WASHER	3 1.82 5.46
FH304576	SPRING TOOTH	3 12.39 37.17
FH311772	Stripper	2 77.75 155.50
FH311995	STRIPPER	1 80.08 80.08
M82222	LOCK NUT M10	3 2.43 7.29
19M8533	M10X25MM ALLEN	3 3.23 9.69
	PARTS	295.19
	LABOR	252.00
16002	SEGMENT TOTAL==>	547.19

SEGMENT#18 C 730 NA	06/26/23 06/26/23	
THIRD BELT FROM LHS IS FREYED BADLY ON EDGE OF BELT -	1.50 HRS	
REPLACE		
***** TECHNICIANS COMMENTS *****		
*	*	
*+replace belt	*	
*	*	

AE74178	DIAMND <529.3">	1 687.08 687.08
	PARTS	687.08
	LABOR	252.00
16002	SEGMENT TOTAL==>	939.08

SEGMENT#19 C 730 NA	06/26/23 07/04/23	
RHS GULLWING DOOR STOPPER ARM IS BENT - STRAIGHTEN	1.00 HRS	
ADJUST BOTH GULL WING DOORS SO THEY CLOSE PROPERLY		
***** TECHNICIANS COMMENTS *****		
*	*	

CONTINUED ON PAGE 09

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X
Signature

Date

Solutions from the Ground Up



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

560M SHF TRD(484562)

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 08/08/23	Time 23:30:22 (B)	Page 09
Account No INTER01	Phone No 7808754471	Inv No S74422
Ship Via		Purchase Order
		Salesperson JAF

DESCRIPTION OF WORK & PARTS

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
030257	560M SUNDERLAND	X 1E0560MDVMN484562	06/02/23		
	560M				

*+removed arm, Bent arm back to proper position and re *
*+installed arm *
*+adjusted doors *
* *

	LABOR	168.00
16002	SEGMENT TOTAL==>	168.00

SEGMENT#20 C 730 NA 06/26/23 06/26/23
LHS NET HOOD ISOLATOR BUMPER MISSING - REPLACE .50 HRS

***** TECHNICIANS COMMENTS *****
* *
*+replaced bumper *
* *

FH334074	Bumper	1	5.12	5.12
	PARTS			5.12
	LABOR			84.00
16002	SEGMENT TOTAL==>			89.12

SEGMENT#21 C 730 NA 06/26/23 06/26/23
DAMAGE - DEERE STICKER IS MISSING FROM REAR HOOD OF NET WRAP .50 HRS
DOOR - REPLACE

***** TECHNICIANS COMMENTS *****
* *
*+cleaned off old glue and installed new sticker *
* *

FH330099	Label	1 N	44.79	44.79
	PARTS			44.79

CONTINUED ON PAGE 10

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X
Signature

Date

Solutions from the Ground Up



www.agland.ca

ST PAUL

Box 1468 • St Paul, AB T0A 3A0
780-645-4437 • 1-877-645-9933

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2
780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4
780-853-5361 • 1-877-853-0922

Ship To:

560M SHF TRD(484562)

Invoice To:

INTERNAL CUSTOMER
Agland
Lloydminster AB T9V 3A2

Branch LLOYDMINSTER		
Date 08/08/23	Time 23:30:22 (B)	Page 10
Account No INTER01	Phone No 7808754471	Inv No S74422
Ship Via		Purchase Order
		Salesperson JAF

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
030257	560M SUNDERLAND 560M	X	1E0560MDVMN484562	06/02/23		

LABOR 84.00

16002

SEGMENT TOTAL==> 128.79

SEGMENT#22 C 730 NA 06/26/23 06/26/23
CHANGE GEAR BOX OIL 1.00 HRS

***** TECHNICIANS COMMENTS *****

*
*+changed oil
*

TY26812	GL5 85w-140 4LT	1	44.72	44.72
			PARTS	44.72
			LABOR	168.00
16002			SEGMENT TOTAL==>	212.72

******* WORK ORDER TOTALS *******

	INTERNAL	CUSTOMER
PARTS	5732.33	
LABOR	5190.53	
SHOP SUPPLIES	250.00	
INTERNAL TOTAL	11172.86	

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

X
Signature

Date

Solutions from the Ground Up