

Experian AutoCheck Report

Report run: 05/06/2026 17:41:52 EDT

2010 Buick Enclave CXL

SUV 4D (3.6L V6 DI Gasoline)

VIN:	5GALRCEDXAJ152512
Class:	CUV - Large
Country of Assembly:	United States
Vehicle Age:	16 year(s)
Estimated In Service:	11/25/2009
Last Reported Odometer:	136,373 (07/02/2020)

Owners - 3



Vehicle Usage
Personal



AutoCheck Score

Similar vehicles usually range between 23 and 38

Vehicle History at a Glance

<p>State Title Brand</p> <p>CLEAN</p>	<p>Auction Brand / Issues</p> <p>NO ISSUE</p>	<p>Accident / Damage</p> <p>DAMAGE REPORTED</p>
<p>Open Recall Check</p> <p>NO OPEN RECALLS</p>	<p>Insurance Loss / Transfer</p> <p>NO ISSUE</p>	<p>Odometer Check</p> <p>Last reported odometer: 136,373 (07/02/2020)</p> <p>NO ISSUE</p>
<p>Certified Pre-Owned</p> <p>NO CPO INFO AVAILABLE</p>	<p>Service / Repair</p> <p>14 Service Record(s) Reported</p> <p>NO ISSUE</p>	<p>Additional History</p> <p>Lien Reported, Corrected Title</p> <p>EVENTS REPORTED</p>



This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)




Accident & Damage




Airbag Deployed


Structural Damage


Overturned


Unknown

Damage Date

Damage Type

Severity

03/30/2019

Collision


Unknown

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.


Service History

Service History Summary


Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

 **Regular Oil Changes**


- 10 oil services reported
- Last oil service reported 12/15/2016

 **Fluids Maintained**


- 3 coolant flushes
- Last fluid maintained 05/20/2015

 **Brakes Maintained**


- 1 brake pad replacements
- Brake last maintained on 08/28/2013

 **Tires Maintained**

Information not available.

 **A/C & Climate Control**

- 3 A/C services reported
- A/C system last serviced 12/15/2016

 **Other Services**

- Cabin air filter replaced on 12/15/2014

OEM Recommended Services



135000 Mile Service

- Change engine oil and filter
- Check engine coolant and windshield washer fluid levels
- Inspect brake system



140000 Mile Service Not Yet Due

- Change engine oil and filter
- Check engine coolant and windshield washer fluid levels
- Inspect brake system

Odometer Check



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2010 Buick Enclave CXL (5GALRCEDXAJ152512) Report Run Date: 05/06/2026 17:41:52 EDT

2009

Owner 1

Location: MI

Owned From: 11/2009

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
11/25/2009	DETROIT, MI	10	Motor Vehicle Dept.	Title(Title #:801X3290023)
11/25/2009	DETROIT, MI		Motor Vehicle Dept.	Registration Event/Renewal
05/31/2010	IL	6,909	Auto Auction	Reported at Auto Auction as Manufacturer Vehicle

2010

Owner 2

Location: IL

Owned From: 09/2010

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
09/03/2010	LISLE, IL		Motor Vehicle Dept.	Registration Event/Renewal
09/16/2010	LISLE, IL	7,200	Motor Vehicle Dept.	Title(Title #:X0259685227) (Lien Reported)
11/04/2010	LISLE, IL		Motor Vehicle Dept.	Registration Event/Renewal
11/02/2011	LISLE, IL		Motor Vehicle Dept.	Registration Event/Renewal
06/27/2012	IL	43,971	Independent Repair Center	Fuel System Serviced Air Filter Changed Multiple Point Vehicle Inspection Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced
10/24/2012	LISLE, IL		Motor Vehicle Dept.	Registration Event/Renewal
10/29/2012	IL	49,564	Independent Repair Center	Cooling System Serviced Multiple Point Vehicle Inspection
01/12/2013	IL	52,955	Independent Repair Center	Vehicle Serviced
02/27/2013	IL	54,261	Independent Repair Center	Multiple Point Vehicle Inspection Lube, Oil And/Or Filter Changed
08/28/2013	IL	60,712	Independent Repair Center	Cooling System Serviced Multiple Point Vehicle Inspection Brakes Serviced Lube, Oil And/Or Filter Changed
10/24/2013	LISLE, IL		Motor Vehicle Dept.	Registration Event/Renewal
01/15/2014	IL	65,072	Independent Repair Center	Multiple Point Vehicle Inspection Lube, Oil And/Or Filter Changed
04/02/2014	IL	66,685	Independent Repair Center	Lights or Signals Serviced
06/28/2014	IL	70,585	Independent Repair Center	Multiple Point Vehicle Inspection Engine Serviced Lube, Oil And/Or Filter Changed
10/08/2014	NAPERVILLE, IL	73,000	Independent Emission Source	Passed Emission Inspection
10/09/2014	LISLE, IL		Motor Vehicle Dept.	Registration Event/Renewal
12/15/2014	IL	74,558	Independent Repair Center	Fuel System Serviced Air Filter Changed Multiple Point Vehicle Inspection Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced
05/20/2015	IL	79,124	Independent Repair Center	Multiple Point Vehicle Inspection Lube, Oil And/Or Filter Changed Vehicle Fluids Serviced
01/20/2016	LISLE, IL		Motor Vehicle Dept.	Registration Event/Renewal
01/22/2016	IL	86,723	Independent Repair Center	Multiple Point Vehicle Inspection Lube, Oil And/Or Filter Changed

Event Date	Location	Odometer	Data Source	Details
04/22/2016	IL	89,934	Independent Repair Center	Multiple Point Vehicle Inspection Engine Serviced Lube, Oil And/Or Filter Changed
07/08/2016	IL	92,603	Independent Repair Center	Multiple Point Vehicle Inspection Engine Serviced
09/21/2016	NAPERVILLE, IL	94,000	Independent Emission Source	Passed Emission Inspection
11/09/2016	LISLE, IL		Motor Vehicle Dept.	Registration Event/Renewal
12/15/2016	IL	98,145	Independent Repair Center	Cooling System Serviced Multiple Point Vehicle Inspection Lube, Oil And/Or Filter Changed
10/24/2017	LISLE, IL		Motor Vehicle Dept.	Registration Event/Renewal
10/16/2018	LISLE, IL		Motor Vehicle Dept.	Registration Event/Renewal
10/16/2018	NAPERVILLE, IL	121,000	Independent Emission Source	Passed Emission Inspection
03/30/2019	CHICAGO, IL		State Agency	Right Side Impact with Another Vehicle(Case #:JC205918)
11/12/2019	LISLE, IL		Motor Vehicle Dept.	Registration Event/Renewal
07/02/2020	IL	136,373	Auto Auction	Reported at Auto Auction



2020

Owner 3

Event Date	Location	Odometer	Data Source	Details
09/02/2020	MORRIS, IL		Motor Vehicle Dept.	Registration Event/Renewal
09/11/2020	MORRIS, IL		Motor Vehicle Dept.	Title(Title #:202556974540) (Lien Reported) Excluded/Exempt
08/02/2021	MORRIS, IL		Motor Vehicle Dept.	Registration Event/Renewal
09/20/2022	MORRIS, IL		Motor Vehicle Dept.	Registration Event/Renewal
04/21/2023	MORRIS, IL		Motor Vehicle Dept.	Title(Title #:231116223250) (Lien Reported) Corrected Title(Lien Reported) Excluded/Exempt

Location: IL

Owned From: 09/2020

Usage: Personal

Warranty Check

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic i	-	-		48 months / 50000 miles
Battery i	-	-	-	Contact a certified dealer to verify coverage
Corrosion i	-	-		72 months / 100000 miles
Powertrain i	-	-		60 months / 100000 miles
Roadside Assistance i	-	-		60 months / 100000 miles

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Safety Restraint ⓘ	-	-	-	Contact a certified dealer to verify coverage

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to **AutoCheck Terms and Conditions**. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (5GALRCEDXAJ152512) qualifies for **AutoCheck Buyback Protection**. If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.