Agland

ë

INTERNAL CUSTOMER

Lloydminster AB T9V 3A2

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

780-853-5361 • 1-877-853-0922

VERMILION 4915 - 47 Avenue • Vermilion, AB T9X 1J4

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933

Ship To:	6175R	NAZZ	TRD(036406)

Branch								
LLOYDMINSTER *REPRINT*								
Date	Time				Page			
06/12/24	23:	30:33	(B)		01			
Account No	Phone No			Inv N	0			
INTER01	780	875447	71	S82	2322			
Ship Via		Purchase (Order					
		152						
	·		Sales	person				
				KIC				

DESCRIPTION OF WORK & PARTS

STK#/FLEET# WARRANTY DATE HRS PIN/EIN HRS 030230 6175R NAZZ CORRAL 4135 1RW6175RTKD036406 04/30/21 2000 PE6068U073023 04/30/23 4000 X 6175R SEGMENT# 1 C 746 NA 05/24/24 05/24/24 INSTALL MILLS TRD LOADER SN:1P0680RXLKC002966 MOUNTS & EVERYTHING NECESSARY TO INSTALL **** TECHNICIANS COMMENTS *********** *+Remove all shields around exhaust *+Remove shields from under & in front of mid *+mount SCV's *+Clean the build up of dirt & straw from around exhaust *+Remove paint from loader mount & frame *+Install RH loader mount & torque bolts *+Touch up paint on frame *+Install bracket for shields back onto frame *+Install new o-rings onto fittings for SCV's *+Remove plugs & install fittings *+Install multi coupler onto loader mount *+Install metal lines onto SCV's *+Install plastic clamp onto lines *+Lines were bent a little bit, straighten so they don't rub *+on the SCV *+Install shields below & in front of mid mount SCV's *+Install shields around exhaust *+Remove paint from LH loader mount & frame *+Install mount, torque bolts *+Touch up paint *+Install shield in front of DEF pump *+Function joystick, 2 functions work but grapple function *+doesn't *+Go into settings, assign SCV to correct button, don't work stCONTINUED ON PAGE 02

• I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.

· Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)

. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

Signature Date

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2

VERMILION

780-875-4471 • 1-877-875-3445

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933 4915 - 47 Avenue • Vermilion, AB T9X 1J4 780-853-5361 • 1-877-853-0922

		Dianch				
[6175R NAZZ TRD(036406)	LLOYDMINSTE	ER			
2		Date	Time			Page
dus		06/12/24	23:	30:33 (B)	02
"		Account No	Phone No		In	v No
L		INTER01	780	8754471	. S	882322
_		Ship Via		Purchase Orc	der	
	INTERNAL CUSTOMER			152		
- U	Agland					
Invoice	Lloydminster AB T9V 3A2					
5					Salesper	son
L					KI	C

DESCRIPTION OF WORK & PARTS

STK#/FLEET# 030230 6175R NAZZ CORRAL 6175R *+Check for code, has active DTC	HRS PIN/EIN 4135 1RW6175RTKD0364 PE6068U073023 - MFC 516446.09	WARRANTY DATE 06 04/30/21 04/30/23 *	HRS 2000 4000 X	Fold
*+Remove armrest from base to acc *+Perform electrical checks on LI	-	* test *		
*+on joystick, good	N bus module clicult	*		
*+Check lead for short circuit to	12V. got 9 volts	*		
*+SA says proceed if "0" or "12"		*		
*+Isolate LIN bus 2, perform same		*		
*+follow, DTAC 111781 for issue	, , , , , , , , , , , , , , , , , , ,	*		
*+Follow solution, no change		*		
*+Last steps says to update ARMC,	HYDS & display	*		
*+Install GEN 4 (24-1) & other ne	eded software	*		
*+Didn't fix issue		*		
*+Set up SCV paddle #4 to run val	ve# 7, works	*		
*+Set up toggle on joystick to ru	n valve# 4	*		
*+SCV# 4 is locked now, believe i	ssue is with joystick	*		
*+Remove armrest again, remove jo	ystick	*		
*+Remove armrest from another tra	ctor, remove joystick	*		
*+Hook up joystick & armrest, tes	t, works now	*		
*+Remove armrest & joystick, inst	all back into donor a	rmrest *		
*+Install armrest back into donor	tractor	*		
*+Order joystick		*		
*+Take tractor outside to install		*		
*+Install multi coupler, went to	close handle & it twi	sted *		
*+off the shaft		*		
*+Tech had changed a multi couple				
*+steel bin, remove handle & clea	n	*		
*+Install into multi coupler		*		
*+Take tractor back outside & ins		*		
*+Remove armrest, install new joy		*		
*+Install armrest back into tract	or	*		
		CONTINUED ON PAG	E 03	
I hereby certify the above work to be done along with the use.	se of necessary materials. You and your	X		

- employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
 It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

Signature Date

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

VERMILION 4915 - 47 Avenue • Vermilion, AB T9X 1J4

780-853-5361 • 1-877-853-0922

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933

 o	6175R NAZZ TRD(036406)
Ship	

INTERNAL CUSTOMER Invoice To: Agland Lloydminster AB T9V 3A2

Branch									
LLOYDMINSTER									
Date	Time				Page				
06/12/24	23:	30:33	(B)		03				
Account No	Phone No			Inv N	0				
INTER01	7808754471			S82	2322				
Ship Via		Purchase	Order						
		152							
			Sales	sperson					
				KIC					

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		прс	PIN/EIN	WA DD:	ANTY DATE	HRS	
·	6175R NAZZ CORRAL		1RW6175RTKD03		04/30/21		Fold
030230	6175R NAZZ CORRAD	4133	PE6068U073023		04/30/21	4000 X	
*+λ11 funat	ions work now		FE00000073023	,	*	4000 X	
*+Top up hy					*		
*+TOP up my	d OII				*		
	******		+++++++++++				
BL15368		Control		1 N	2799.05	2799.05	
FRT			CHARGES	1 N	20.00	2799.03	
		_		7	20.00 7.89		
HY-GARD		HY-GARD	=	-		55.23	
T77857		F/F-ORII		6	3.02	18.12	
51M7045		O-RING I	M22	6	5.64	33.84	
					PARTS	2926.24	
					LABOR	4770.24	
	16000			SEGMENT	TOTAL==>	7696.48	
**** TECHN	746 NA L INDICATOR ROD MI ICIANS COMMENTS **	SSING - R		****	***		
*					*		
	brought in rod & b	racket			*		
_	n bracket & rod				*		
	ng washer & spacer	_	ts		*		
*+Install l	evel indicator rod	l			*		
*					*		
******	******	*****	******	*****	***		
A22724		WASHER-I	HARDENED	1	5.47	5.47	
24M7180		FLATWASI	HER-13MM	1	2.62	2.62	
					PARTS	8.09	
					LABOR	103.20	
	16000			SEGMENT	TOTAL==>	111.29	
SEGMENT# 3 C	746 NA	05/24/24	4 06/03/24				· · · · · · · · · · · · · · · · · · ·

• I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an

express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.

Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

CONTINUED ON PAGE 04

Date Signature

Agland

Lloydminster AB T9V 3A2

ë

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

<u>VERMILION</u> 4915 - 47 Avenue • Vermilion, AB T9X 1J4

780-853-5361 • 1-877-853-0922

ST PAUL

Box 1468 • St Paul, AB T0A 3A0 780-645-4437 • 1-877-645-9933

Ship To:	6175R NAZZ TRD(036406)
	INTERNAL CUSTOMER

Branch					
LLOYDMINSTER	1				
Date	Time				Page
06/12/24	23:	30:33	(B)		04
Account No	Phone No			Inv N	0
INTER01	780	875447	71	S82	2322
Ship Via		Purchase (Order		
		152			
			Sales	person	
				KIC	

DESCRIPTION OF WORK & PARTS

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS 030230 6175R NAZZ CORRAL 4135 1RW6175RTKD036406 04/30/21 2000 4000 X 6175R PE6068U073023 04/30/23 7 LOADER PIN WON'T TAKE GREASE - REMOVE & CLEAN GREASE PORTS IN PINS REPLACE LEAKING GREASE LINE ON RH SIDE OF LOADER **** TECHNICIANS COMMENTS **************** *+Remove grease lines, clamps & brackets *+Install grease zerks into pins, grease pins *+Remove bucket grapple , multi coupler won't come apart *+Pins are siezed into bores, get separated *+Remove pins from multi coupler *+Clean pins & bores *+Remove bottom pivot pins on global carrier, remove zerks *+Drill out grease holes, clean debris from pins *+Install zerks, pump grease through pins *+Install pins in carrier, install lock pins & cotter pin *+Grease both pins *+Remove bolts, rubber seal & washers from pin in *+bucket cylinder & bellcrank *+Support boom linkage with straps *+Remove pin from cylinder *+Then slide pin out of inner bellcrank, remove snap ring *+Remove pin & inner bellcrank from linkage *+Remove pin from outer bellcrank, remove snap ring *+Remove pin & outer bellcrank from linkage *+Remove grease zerks from inner & outer boom linkage *+Drill out hardened grease, install grease zerks *+Assemble all components back together *+Complete same procedure for the other side of loader *+Remove grease zerks from grapple pivots *+Clean out port, grease zerks are plugged solid CONTINUED ON PAGE 05 • I hereby certify the above work to be done along with the use of necessary materials. You and your

I hereby certify the above work to be done along with the use of necessary materials. You and your
employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I
agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an
express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.

 Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)

It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

Signature Date



Invoice To:

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

75-3445 <u>VERMILION</u>

4915 - 47 Avenue • Vermilion, AB T9X 1J4

780-853-5361 • 1-877-853-0922

KIC

ST PAUL

Box 1468 • St Paul, AB T0A 3A0 780-645-4437 • 1-877-645-9933

6175R	NAZZ	TRD(036406)	

Branch LLOYDMINSTER Date Time Page 06/12/24 23:30:33 (B) 05 Account No Inv No INTER01 7808754471 S82322 Ship Via Purchase Order 152 Salesperson

INTERNAL CUSTOMER Agland Lloydminster AB T9V 3A2

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		PIN/EIN		ANTY DATE	HRS	Fold
030230 6175R NAZZ CORRAL	4135	1RW6175RTKD03		04/30/21	2000	
6175R		PE6068U073023	3	04/30/23	4000 X	
*+Install new grease zerks on	both side	es		*		
*+Grease pins				*		
*				*		
**********					0.00	
JD7798	GREASE 2	ZERK	2	1.46	2.92	
				PARTS	2.92	
				LABOR	1709.34	
16000			SEGMENT	TOTAL==>	1712.26	
SEGMENT# 4 C 746 NA	05/24/24	1 06/06/24				
HOSE GOING TO GRAPPLE MULTI C	OUPLER IS	LEAKING & BEI	NT			
DIAGNOSIS & REPAIR						
**** TECHNICIANS COMMENTS **	*****	*****	****	***		
*				*		
*+Straighten bent line				*		
*+Remove hose, replace damage	d o-rings	on hose		*		
*+Function loader to verify no	-			*		
*				*		
*******	*****	****	*****	***		
т77857	F/F-ORI	NG #8	2	3.02	6.04	
	·			PARTS	6.04	
				LABOR	209.84	
16000			SEGMENT	TOTAL==>	215.88	
SEGMENT# 5 C 746 NA	05/24/2/	1 06/04/24				
BOTH GRAPPLE CYLINDERS ARE L		, ,				
**** TECHNICIANS COMMENTS **						
* TECHNICIANS COMMENTS **				*		
*IDomorro bred linea from arrlin	dona			*		
*+Remove hyd lines from cyline				*		
*+Remove cylinders from grapp	Te		COMM	INUED ON PA	CE 06	
			CONT	INOED ON PA	GE 00	
 I hereby certify the above work to be done along with employees may operate above machine for purposes 				X		
agree to pay cash on delivery of machine or on term	s satisfactory with	yoù and until paid in ful	l an	Signature		Date
express mechanic's lien is acknowledged on above ma • Terms: Full payment due immediately upon completio						
at the rate of 1.5% per month (18% per annum) • It is understood that this company assumes no response.	onsibility for loss (or damage by theft or fir	e to			
machine placed with them for storage, sale, repair, or			C 10			

Agland

Invoice To:

INTERNAL CUSTOMER

Lloydminster AB T9V 3A2

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

Branch

VERMILION 4915 - 47 Avenue • Vermilion, AB T9X 1J4

780-853-5361 • 1-877-853-0922

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933

6175R NAZZ TRD (036406) Ship To:

Branen					
LLOYDMINSTER					
Date	Time				Page
06/12/24	23:	30:33	(B)		06
Account No	Phone No			Inv N	0
INTER01	780	875447	71	S82	2322
Ship Via		Purchase (Order		
		152			
			Sales	person	
				KIC	

DESCRIPTION OF WORK & PARTS

STK#/FLEET#			PIN/EIN		ANTY DATE	HRS	Fold
	R NAZZ CORRAL	4135			04/30/21		
617			PE6068U07302	23	04/30/23	4000 X	
	ylinder & clean a	_			*		
	eals & o-rings &		le		*		
-	der, hook up hose				*		
	ylinder for other				*		
-	ide for piston is			v piston	*		
	eals & o-rings on	_	uide		*		
*+Install new p	iston, torque nut				*		
-	nder & install ho	ses			*		
	der onto grapple				*		
*+Hook up all h	oses & secure wit	h zipt	ies		*		
*					*		
******	******	*****	*****	*****	* * *		
AH142159	F	ISTON		1 N	135.94	135.94	
AH161589	H	YD.CYL	.KIT	2	81.57	163.14	
AH212088	K	IT		2	65.78	131.56	
FRT	F	REIGHT	CHARGES	1	20.00	20.00	
M86436	T	'IE BAN	D-28"	2	2.10	4.20	
6624289	S	TRAP,T	IE	4	1.82	7.28	
					PARTS	462.12	
					LABOR	860.00	
	16000			SEGMENT	TOTAL==>	1322.12	
SEGMENT# 6 C 746	NA 0	5/24/2	4 05/24/24				
REPLACE EXPAND	ED METAL ON GRAPE	LE SCR	EEN & STRAIG	HTEN			
2 GRAPPLE TINES	ARE BENT - STRAI	GHTEN					
**** TECHNICIA	NS COMMENTS ****	*****	*****	*****	* * *		
•					4		

• I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.

*+Remove 3 grapple tines, straighten & install

*+Remove grapple screen & straighten

*+repair silage screen

Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

Signature Date

CONTINUED ON PAGE 07



LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

VERMILION 4915 - 47 Avenue • Vermilion, AB T9X 1J4

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933

Ship To:	6175R NAZZ TRD(036406)
e To:	INTERNAL CUSTOMER Agland

Lloydminster AB T9V 3A2

Branch								
LLOYDMINSTER								
Date	Time				Page			
06/12/24	23:	30:33	(B)		07			
Account No	Phone No			Inv N	0			
INTER01	8754471 S8			2322				
Ship Via	Ship Via			Purchase Order				
		152						
			Sales	person				
				KIC				

780-853-5361 • 1-877-853-0922

DESCRIPTION OF WORK & PARTS

STK#/FLEET#	HRS F	PIN/EIN	WAR	RANTY DATE	HRS	Fold
030230 6175R NAZZ CORRAL		.RW6175RTKD				Fold
6175R		E6068U07302		04/30/23		
*+Install grapple screen & insta				*		
*				*		
********	*****	*****	*****	***		
				LABOR	745.45	
16000			SEGMEN'	r TOTAL==>	745.45	
		06/06/24				
HYDRAULIC LEAK AT REAR OF TRACTO	_					
**** TECHNICIANS COMMENTS ****	******	*****	*****			
*				*		
*+Lots of oil around SCV covers				*		
*+Remove all 4 SCV dust covers				*		
*+wash off rear of tractor				*		
*+Hook up flow meter, heat up oi	11			*		
*+Flow oil on SCV# 1 & 2				*		
*+Found SCV# 2 retract coupler i		ng on outsid	de of bo	dy *		
*+Flow oil on SCV# 3 & 4, no iss	sues			*		
*+R&R coupler body & seals on SC	CV# 2 ret	ract		*		
*+Flow SCV# 2 again, good				*		
*+Clean all SCV dust covers & in	nstall			*		
*+Tighten all hose clamps for pu	ımp sucti	on & the		*		
*+return lines at rear of tracto	or			*		
*				*		
********	******	*****	*****	***		
AL213391 H	Hydr. Qui	.ck Cou	1	236.88	236.88	
				PARTS	236.88	
				LABOR	636.40	
16000			SEGMEN'	r TOTAL==>	873.28	

• I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.

Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

***** WORK ORDER TOTALS *****

CONTINUED ON PAGE 08 Signature

Date



LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2

VERMILION

780-875-4471 • 1-877-875-3445

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933 4915 - 47 Avenue • Vermilion, AB T9X 1J4 780-853-5361 • 1-877-853-0922

6175R NAZZ TRD(036406) LLOYDMINSTER	
01/5K MAZZ TRD (050400)	
<mark>င</mark> ္ Date Time P	Page
06/12/24 23:30:33 (B) (C)	08
Account No Phone No Inv No	
INTER01	322
Ship Via Purchase Order	
internal customer 152	
Lloydminster AB T9V 3A2 Salesperson	
Salesperson	
KIC	

DESCRIPTION OF WORK & PARTS

STK#/FLEET#			HRS	PIN/EIN	WARRANTY DATE	HRS	Fold
030230	6175R NAZZ	CORRAL	4135	1RW6175RTKD03640	06 04/30/21	2000	
	6175R			PE6068U073023	04/30/23	4000 X	
						INTERNAL	CUSTOMER
					PARTS	3642.29	
					LABOR	9034.47	
					SHOP SUPPLIES	250.00	
				<u>-</u>	INTERNAL TOTAL	12926.76	

Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

Signature

[•] I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.

Agland

ë

INTERNAL CUSTOMER

Lloydminster AB T9V 3A2

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

VERMILION 4915 - 47 Avenue • Vermilion, AB T9X 1J4

780-853-5361 • 1-877-853-0922

-3445 VFRMILTO

ST PAUL

Box 1468 • St Paul, AB T0A 3A0 780-645-4437 • 1-877-645-9933

Ship To:	IN	STORE	PICKUP		

Branch								
LLOYDMINSTER	1	*REPF	*TNI					
Date	Time				Page			
04/30/24	23:	30:57	(B)		01			
Account No	Phone No			Inv N	0			
INTER01	INTER01 780			8754471 S81				
Ship Via	Ship Via			Purchase Order				
		•	Sales	person				
				DJB				

DESCRIPTION OF WORK & PARTS STK#/FLEET# WARRANTY DATE HRS PIN/EIN HRS 030230 6175R NAZZ CORRAL 4135 1RW6175RTKD036406 04/30/21 2000 PE6068U073023 04/30/23 4000 X 6175R SEGMENT# 1 C 743 NA 03/26/24 03/28/24 TRACTOR WON'T START - DIAGNOSE AND REPAIR POSSIBLY PARTS WARRANTY - BATTERY WAS REPLACED IN DECEMBER **** TECHNICIANS COMMENTS ********************** *+Confirmed glow plug circuit appears to be working *+Attempted to start and engine cranks very slow *+After 1 attempt engine would not turn over *+Used service truck to boost battery *+After about 15-min tractor started and ran without issue *+Allowed engine to run and charge up battery *+Load tested with hand held tester *+Battery passed load test but CCA showed 1080cca battery *+is rated for 1400cca *+Removed steps & battery *+Removed several caps and confirmed battery is not *+Brought battery into shop and let sit on trickle *+charger over night *+Load test in morning and battery now showed 86% *+capacity *+Advised Dawson on battery condition *+Informed to let parts department to trickle charge on *+there machine and see if battery tests better *+Re-installed battery *+Re-installed step *+Operated and engine started without issue CONTINUED ON PAGE 02

I hereby certify the above work to be done along with the use of necessary materials. You and your
employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I
agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an
express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.

Terms: Full payment due immediately upon completion of work or service charge on overdue account
at the rate of 1.5% per month (18% per annum)

 It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing. Signature Date



Agland

Lloydminster AB T9V 3A2

ë

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

VERMILION

<u>VERMILION</u> 4915 - 47 Avenue • Vermilion, AB T9X 1J4 780-853-5361 • 1-877-853-0922

ST PAUL

Box 1468 • St Paul, AB T0A 3A0 780-645-4437 • 1-877-645-9933

.o⊤	IN STORE PICKUP
Ship	
	INTERNAL CUSTOMER

Branch								
LLOYDMINSTER								
Date	Time				Page			
04/30/24	23:	30:57	(B)		02			
Account No	Phone No			Inv N	0			
INTER01	780	71	S81170					
Ship Via	Purchase Order							
			Sales	person				
				DJB				

DESCRIPTION OF WORK & PARTS

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS Fold 030230 6175R NAZZ CORRAL 4135 1RW6175RTKD036406 04/30/21 2000 4000 X 6175R PE6068U073023 04/30/23 ************************* LABOR 381.84 16000 SEGMENT TOTAL ==> 381.84 SEGMENT# 2 C 716 03/26/24 04/04/24 NA PLC 523961.07 - ACTIVE - DIAGNOSE AND REPAIR **** TECHNICIANS COMMENTS ************* *+code PLC 523961.07 is not active *+code MFC 516446.09 is active *+after going through all the diagnostic steps *+testing valves & sensors *+disconnected the ground cable at battery *+waited 10 minutes over coffee break *+connect ground cable *+tractor drives now *+remove ground cable at battery & at frame *+look over cable & it's good *+clean up cable & frame *+install cable *+there's one wire attached to the ground cable *+the eye let on the wire wasn't in good shape *+so replaced the eye let *+connected wire to ground and tighten bolt *+run tractor and it drives with no codes *+check all ground cables on the outside of tractor *+clear code *+start tractor and check codes *+TIA 523961.02 and PLC 523961.02 are active with computer *+connected CONTINUED ON PAGE 03

• I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.

Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)

It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

Signature Date

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4

780-853-5361 • 1-877-853-0922

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933

Ship To:	IN	STORE	PICKUP

INTERNAL CUSTOMER Invoice To: Agland Lloydminster AB T9V 3A2

Branch								
LLOYDMINSTER								
Date	Time				Page			
04/30/24	23:	30:57	(B)		03			
Account No	Phone No			Inv N	0			
INTER01	780	1	S81170					
Ship Via	Purchase Order							
		Sales	person					
				DJB				

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		HRS	PIN/EIN	WARR	ANTY DATE	HRS	Fold
030230	6175R NAZZ CORRAL	4135	1RW6175RTKD036	406	04/30/21	2000	
	6175R		PE6068U073023		04/30/23	4000 X	
*+go throu	gh trouble shooting te	st			*		
*+Y16-2 is	not reading proper				*		
*+check co	nnection at y16-2 park	lock	solenoid		*		
*+remove y	16-2 solenoid and check	k o ri	ngs, good		*		
*+remove x	987f-1 connector from :	rear c	ontrol unit		*		
*+load tes	t wires wires and good				*		
*+check re	sistance on solenoid,	good			*		
*+look for	solution for codes TI	A and	PLC 523961.02		*		
*+found so	lution 118110				*		
*+solution	said to replace park	lock p	ressure sensor		*		
*+start co	nnecting everything und	did to	do all the tes	ting	*		
*+install	new sensor				*		
*+connect	electrical				*		
*+connect	computer to tractor				*		
*+turn key	on and clear codes				*		
	actor and put into neu	tral			*		
*+no code	came up				*		
*+place in	to park, no code				*		
*+move to	neutral and no code				*		
*+move lev	er to center position a	and no	code		*		
*+install	rear wheel, tighten and	d torq	ue bolts		*		
*+install	RH ladder				*		
*+return t	ools				*		
*+test dri	ve tractor, stop and s	tarts			*		
*+no codes					*		
*+retorque	wheel bolts				*		
	ctor at front line up				*		
*					*		
******	*****	*****	******	****	***		
RE584415	P	ressur	e Sensor	1 N	168.09	168.0	9
				CONT	INUED ON PAG	E 04	
I hereby certify	the above work to be done along with the	use of nece	ssary materials. You and vou		X		

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
 It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

^	
Signature	Date



Agland

Invoice To:

INTERNAL CUSTOMER

Lloydminster AB T9V 3A2

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

VERMILION

4915 - 47 Avenue • Vermilion, AB T9X 1J4

780-853-5361 • 1-877-853-0922

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933

Ship To:	IN	STORE	PICKUP

Branch					
LLOYDMINSTER	-				
Date	Time				Page
04/30/24	23:	30:57	(B)		04
Account No	Phone No			Inv N	0
INTER01	780	875447	1	S81	L170
Ship Via		Purchase (Order		
			Sales	person	
				DJB	

DESCRIPTION OF WORK & PARTS

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS 030230 4135 2000 6175R NAZZ CORRAL 1RW6175RTKD036406 04/30/21 4000 X 6175R PE6068U073023 04/30/23 PARTS 168.09 3666.70 LABOR 16000 SEGMENT TOTAL ==> 3834.79

**** WORK ORDER TOTALS *****

INTERNAL CUSTOMER PARTS 168.09 4048.54 LABOR SHOP SUPPLIES 250.00 INTERNAL TOTAL 4466.63

Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
It is understood that this company assumes no responsibility for loss or damage by theft or fire to

machine placed with them for storage, sale, repair, or while field testing.

Signature

[•] I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.



LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2

Branch

VERMILION

780-875-4471 • 1-877-875-3445

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933 www.agland.ca

4915 - 47 Avenue • Vermilion, AB T9X 1J4 780-853-5361 • 1-877-853-0922

6175R NAZZ TRD(036406)	LLOYDMINSTER	R *REPRI	NT*
Ship To:	Date	Time	Page
<u>σ</u>	02/28/24	23:30:23 (3) 01
\overline{o}	Account No	Phone No	Inv No
	INTER01	7808754471	S79333
	Ship Via	Purchase Orde	
: INTERNAL CUSTOMER		019	
Agland			
G INTERNAL CUSTOMER g Agland G Lloydminster AB T9V 3A2			
>			Salesperson
			JAF
DESCRIPTION OF WOR	RK & PARTS		
STK#/FLEET# HRS PIN/EIN	WARRANTY DATE	E HRS	Fold
030230 6175R NAZZ CORRAL 4130 1RW6175RTKD036		2000	Fold
6175R PE6068U073023	•	3 4000 X	
01/310	01/30/23	1000 11	
SEGMENT# 1 C 468 10-000-300 10/23/23 12/21/23			
PERFORM TRACTOR TRADE INSPECTION AS PER CHECKLIST	8.0	00 HRS	
-SEE ATTACHED CHECKLIST			
-ALL TRACTOR CLEANING AND CAB CLEANING TO BE DONE ON	A		
SEPARATE SEGMENT			

RECORD IN COMMENTS:			
DYNO READING: HP			
HYDRAULIC READING:GPM @ 1500 RPM			
-INSTALL A BAG OF THE MOUSE FRAGRANCE TO THE CAB TO D	ETER		
RODENT INFESTATION			
************	**		
NOTE: GLOW PLUGS DON'T SEEM TO BE WORKING			
*************	***		
**** TECHNICIANS COMMENTS ***************	*****		
*	*		
*+Performed trade inspection	*		
*	*		
*************	*****		
	LABOR	1344.00	
16000	SEGMENT TOTAL==>	1344.00	
SEGMENT# 2 C INTER 10-000-003 10/23/23			
CLEAN AND WASH EXTERIOR - TRADE TRACTOR	3.0	00 HRS	
TOUCH UP PAINT ON TRACTOR	3.0		
GREASE MACHINE ENTIRELY AFTER WASH			
PARK IN LINE UP			
**** TECHNICIANS COMMENTS ***************	*****		
*	*		

• I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.

Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
It is understood that this company assumes no responsibility for loss or damage by theft or fire to

machine placed with them for storage, sale, repair, or while field testing.

Date Signature

CONTINUED ON PAGE 02



LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

VERMILION
4915 - 47 Avenue • Vermilion, AB T9X 1J4

780-853-5361 • 1-877-853-0922

ST PAUL

Box 1468 • St Paul, AB T0A 3A0 780-645-4437 • 1-877-645-9933

	6175R	NAZZ	TRD (036406)
<u> </u>			
≘			
S			

INTERNAL CUSTOMER

By Agland

Lloydminster AB T9V 3A2

employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an

express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.

• Terms: Full payment due immediately upon completion of work or service charge on overdue account

· It is understood that this company assumes no responsibility for loss or damage by theft or fire to

at the rate of 1.5% per month (18% per annum)

machine placed with them for storage, sale, repair, or while field testing.

Branch					
LLOYDMINSTER	2				
Date	Time				Page
02/28/24	23:	30:23	(B)		02
Account No	Phone No			Inv N	0
INTER01	780	875447	71	S79	9333
Ship Via		Purchase (Order		
		019			
			Sales	person	
				JAF	

DESCRIPTION OF WORK & PARTS STK#/FLEET# PIN/EIN WARRANTY DATE HRS HRS 030230 6175R NAZZ CORRAL 4130 1RW6175RTKD036406 04/30/21 2000 PE6068U073023 04/30/23 4000 X 6175R *+washbay to do 10/23/23 12/27/23 SEGMENT# 3 C 468 INSTALL 3 POINT HITCH LINKAGE 3 POINT HITCH WILL NOT GO DOWN DIAGNOSE & REPAIR **** TECHNICIANS COMMENTS ******************** *+Installed 3pt hitch linkage and pins as needed. *+Old pins seized in 3pt lift cylinders. *+Pounded out pins and lubricated bores. *+Installed needed linkage and pins. *+Used chain hoist to retract cylinders. *+Cycled 3py hitch multiple times to ensure operation. OK LABOR 614.88 16000 614.88 SEGMENT TOTAL ==> 10/23/23 12/27/23 SEGMENT# 4 C 468 NA COMPLETE SERVICE CHANGE ENGINE OIL & FILTERS CHANGE FUEL FILTERS CHANGE ALL AIR FILTERS CHANGE HYD/TRANS FILTERS DOUBLE CHECK FLUID LEVELS & GREASE **** TECHNICIANS COMMENTS ***************** *+R+R engine oil and filter CONTINUED ON PAGE 03 • I hereby certify the above work to be done along with the use of necessary materials. You and your

Solutions from the Ground Up

Signature

Agland

Invoice To:

INTERNAL CUSTOMER

Lloydminster AB T9V 3A2

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

VERMILION 4915 - 47 Avenue • Vermilion, AB T9X 1J4 780-853-5361 • 1-877-853-0922

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933

Ship To:	으 료 료	(036406)

Branch						
LLOYDMINSTER						
Date	Time				Page	
02/28/24	23:	30:23	(B)		03	
Account No	Phone No			Inv N	0	
INTER01	780	875447	71	S79	9333	
Ship Via		Purchase (Order			
		019				
			Sales	person		
				πΔT.		

DESCRIPTION OF WORK & PARTS

STK#/FLEET#		HRS	PIN/EIN	WARF	RANTY DATE	HRS	Fold
030230	6175R NAZZ CORRAL	4130	1RW6175RTKD03		04/30/21		
	6175R		PE6068U073023	3	04/30/23	4000 X	
*+R+R both	engine air filters				*		
*+R+R tran	smission filter				*		
*+R+R hyd	filter				*		
*+R+R HVAC	filter				*		
*+Blew out	HVAC screen filters	•			*		
*+Greased	unit complete				*		
*+R+R CCV	filter.				*		
*+Topped u	p hyd oil level.				*		
*					*		
******	*****	*****	*****	*****	****		
AL206482		TRAN.FI	LTER IVT	1	101.70	101.70	
AL215053		Air Fil	ter	1	212.55	212.55	
AL215054		SEC. FI	LTER	1	103.14	103.14	
AL220527		CAB Fil	ter	1	84.08	84.08	
AL232898		HYD.FIL	TER	1	186.06	186.06	
DZ105100		VENT FI	LTER	1	78.42	78.42	
DZ115391		FUEL FI	LTER	1	67.89	67.89	
DZ115392		FILTER,	FUEL	1	74.92	74.92	
HY-GARD		HY-GARD	OIL	18	7.89	142.02	
L214634		CAB FIL	.(QTY.2)	2	46.14	92.28	
NPN		Schrade	r Valve	1	6.30	6.30	
RE523251		22MM DR	AIN PLUG	1	25.08	25.08	
RE539279		OIL FIL	TER	1	44.59	44.59	
R502513		SEAL		1	13.18	13.18	
TY26673		15w40+5	0II 3.8L	1	32.49	32.49	
TY26674		15W40+5	0II946ML	1	8.37	8.37	
TY26675		15W40+5	0II 9.5L	2	80.15	160.30	
					PARTS	1433.37	
					LABOR	1008.00	
	16000			SEGMENT	T TOTAL==>	2441.37	
				CONT	TINUED ON PA	GE 04	

• I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.

Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

Date Signature



LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

780-853-5361 • 1-877-853-0922

VERMILION 4915 - 47 Avenue • Vermilion, AB T9X 1J4

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933

: 6175R NAZZ TRD(036406)

INTERNAL CUSTOMER ë Agland Lloydminster AB T9V 3A2

Branch					
LLOYDMINSTER	2				
Date	Time				Page
02/28/24	23:	30:23	(B)		04
Account No	Phone No			Inv N	0
INTER01	780	875447	1	S79	9333
Ship Via		Purchase (Order		
		019			
			Sales	person	
				JAF	

DESCRIPTION OF WORK & PARTS STK#/FLEET# PIN/EIN WARRANTY DATE HRS HRS 030230 4130 6175R NAZZ CORRAL 1RW6175RTKD036406 04/30/21 2000 PE6068U073023 04/30/23 4000 X 6175R SEGMENT# 5 C 468 10/23/23 12/27/23 CHANGE MFWD OILS **** TECHNICIANS COMMENTS ******* *+R+R MFWD axle oils HY-GARD OIL 15 7.89 118.35 HY-GARD NPNDIFF ADDITIVE 1 16.50 16.50 Z104508 Sealing Washer 2 7.20 3.60 PARTS 142.05 336.00 LABOR 16000 SEGMENT TOTAL ==> 478.05 10/23/23 12/27/23 SEGMENT# 6 C 468 CHANGE BATTERIES BATTERIES FAILED LOAD TEST & ENGINE CRANKS SLOW **** TECHNICIANS COMMENTS *********** *+Removed RH step to get access to battery. Had to cut bolts * *+Removed cables from battery. *+Removed battery hold down bracket. *+Cleaned out battery compartment of dirt built up. *+Installed new battery. Installed hold down bracket. *+Cleaned cables and installed on battery. *+Installed RH step with new hardware as needed 54.00-**BCORE** BATTERY CORE 54.00 CONTINUED ON PAGE 05

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- · Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- · It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

Signature Date

LLOYDMINSTER

Box 10039 . Lloydminster, AB T9V 3A2

VERMILION

780-875-4471 • 1-877-875-3445

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933 4915 - 47 Avenue • Vermilion, AB T9X 1J4 780-853-5361 • 1-877-853-0922

		Diancii				
	6175R NAZZ TRD(036406)	LLOYDMINSTE	lR.			
<u>:</u>		Date	Time			Page
S P		02/28/24	23:	30:23 (B)	05
"		Account No	Phone No		Inv	No
L		INTER01	780	8754471	S	79333
_		Ship Via		Purchase Order	-	
<u></u>	INTERNAL CUSTOMER			019		
	Agland					
Invoice	Lloydminster AB T9V 3A2					
5				S	alesperso	on
L					JAI	F
				•		

DESCRIPTION OF WORK & PARTS STK#/FLEET# PIN/EIN WARRANTY DATE HRS HRS 030230 2000 6175R NAZZ CORRAL 4130 1RW6175RTKD036406 04/30/21 PE6068U073023 04/30/23 4000 X 6175R TY26783B 1400CCA/D5/BATT 1 807.12 807.12 PARTS 753.12 LABOR 330.96 16000 1084.08 SEGMENT TOTAL ==> SEGMENT# 7 C 468 NA 10/23/23 12/27/23 ENGINE ACCESSORY DRIVE TENSIONER IDLER IS FAILED - REPLACE **** TECHNICIANS COMMENTS ********************** *+Removed engine accessory drive tension idler. *+Removed belt tension. *+Removed tension idler *+Installed new tension idler. Torqued bolt 37ft/lbs *+Installed belt. Ensured alignment. OK AL181832 291.09 Tightener 1 291.09 PARTS 291.09 225.12 LABOR 16000 SEGMENT TOTAL ==> 516.21 SEGMENT# 8 C 468 10/23/23 01/02/24 NA UPDATE SOFTWARE **** TECHNICIANS COMMENTS ************* *+Update software LABOR 252.00 16000 SEGMENT TOTAL ==> 252.00 CONTINUED ON PAGE 06

- I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.
- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
- . It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

Signature Date



LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

LLOYDMINSTER

Branch

VERMILION

ST PAUL

Box 1468 • St Paul, AB TOA 3A0

ww.agland.ca	780-645-4437 • 1-877-645-9933

6175R NAZZ TRD (036406)

915 - 4/	Avenue •	٧	ermilion	i, AB	19X	1J ²
780-8	353-5361	•	1-877-8	353-09	922	

₽			Date		Time			Page
Ship To			02/	28/24	23:	30:23 (B	.)	06
σ			Account I		Phone No	,	Inv N	10
			INT	ER01	780	8754471	s79	9333
			Ship Via		1	Purchase Order	r	
: INTERNAL CUSTO)MER					019		
β Agland								
Agland Lloydminster A	AB T9V 3A2							
vr						s	alesperson	 I
							JAF	
	DESC	RIPTION OF WOR	K & P	ARTS				
STK#/FLEET#	UDG	PIN/EIN	TAT A D D	ANTY DATE	י ד	IRS		
030230 6175R NAZZ (1RW6175RTKD036		04/30/21		000		Fold
6175R NAZZ (ORRAL 4130	PE6068U073023	400	04/30/23		000 X		
01/3R		PE00000073023		04/30/23	9 40	700 A		
SEGMENT# 9 C 468 NA		3 01/02/24						
TWINE WRAPPED IN RH REA								
**** TECHNICIANS COMME	INTS ********	*****	*****					
*				*				
*+Removed twine from re	ar axle both si	des		*				
*				*				
********	:*****	*****	*****					
				LABOI		168.00		
16000)	S	EGMENT	TOTAL==>	>	168.00		
CECMENTE 10 C 460 NA	10/22/2	2 01/02/24						
SEGMENT#10 C 468 NA		3 01/02/24						
LH DOOR LATCH STICKY/HA **** TECHNICIANS COMME			+++++	. 4 4 4				
*	MID			*				
*+Adjusted door latch				*				
*+Adjusted door laten				*				
********		*****	*****					
				LABOI	.	84.00		
16000	١	c	ECMENT	TOTAL==		84.00		
10000	,	S	EGMENT	IOIAL		04.00		
SEGMENT#11 C 468 NA		3 12/27/23						
SMV SIGN MISSING - REPI								
**** TECHNICIANS COMME	INTS ********	*****	*****					
*				*				
*+Assembled and install	_ed new SMV sign			*				
*				*				

JD5929	SMV EMB	LEM	1	30.09		30.09		
L204973	Angle		1	61.62		61.62		
			CONT	INUED ON	PAGE (7		
 I hereby certify the above work to be do employees may operate above machine 				X Cianatum				
agree to pay cash on delivery of machin				Signature				Date

Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair, or while field testing.

express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.

LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2 780-875-4471 • 1-877-875-3445

VERMILION 4915 - 47 Avenue • Vermilion, AB T9X 1J4

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933

Ship To:	6175R NAZZ TRD(036406)
voice To:	INTERNAL CUSTOMER Agland Lloydminster AB T9V 3A2

Branch					
LLOYDMINSTER	<u>.</u>				
Date	Time				Page
02/28/24	23:	30:23	(B)		07
Account No	Phone No			Inv N	0
INTER01	780	875447	71	S79	9333
Ship Via		Purchase	Order		
		019			
			Sales	person	
				JAF	

780-853-5361 • 1-877-853-0922

DESCRIPTION OF WORK & PARTS

STK#/FLEET# 030230	6175R NAZZ 6175R	CORRAL	HRS 4130	PIN/EIN 1RW6175RTK PE6068U073	D036406	ANTY DATE 04/30/21 04/30/23	HRS 2000 4000 X	Fold
14M7165			LOCK NU	Г	2	.68	1.36	
19M7077			BOLT-M62	X20MM	2	.79	1.58	
24M7054			FLATWASI	HER-6MM	2	.26	.52	
						PARTS	95.17	
						LABOR	84.00	
	1600	00			SEGMENT	TOTAL==>	179.17	

SEGMENT#12 C 468 NA 10/23/23 12/28/23

WINDSHIELD WASHER FLUID TANK IS DAMAGED - REPLACE

- +Removed needed shields and bracket to remove tank.
- +Removed tank.
- +Marked and removed harness and hoses from pumps.
- +Had to straightened 2 bracket to get new tank to fit.
- +Installed all removed components.
- +Installed exhaust shields, side step, battery shields
- +Filled with washer fluid.
- +Tested operation. OK

<u></u>					
AL231622		Reservoir	1 N	329.38	329.38
L102357		NUT	1	3.82	3.82
TY27865		WASHER FLUID	1	7.91	7.91
VGA10885		RIVET	1	1.34	1.34
14M7299		NUT-12MM FLG HD	1	2.49	2.49
19M7775		FL/BOLT-M6X16MM	2	1.28	2.56
19M7788		FL/BOLT-M12X25M	1	2.60	2.60
				PARTS	350.10
				LABOR	529.20
	16000		SEGMENT	TOTAL==>	879.30

***** WORK ORDER TOTALS *****

CONTINUED ON PAGE 08

Signature Date

- Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
 It is understood that this company assumes no responsibility for loss or damage by theft or fire to
- machine placed with them for storage, sale, repair, or while field testing.

ullet I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.



LLOYDMINSTER

Box 10039 • Lloydminster, AB T9V 3A2

VERMILION

780-875-4471 • 1-877-875-3445

ST PAUL

Box 1468 • St Paul, AB TOA 3A0 780-645-4437 • 1-877-645-9933

4915 - 47 Avenue • Vermilion, AB T9X 1J4 780-853-5361 • 1-877-853-0922

	6175R NAZZ TRD(036406)		LLOYDMINS
To:			Date
Ship			02/28/24
(i)			Account No
		'	INTER01
		. [Ship Via
To:	INTERNAL CUSTOMER		
	Agland		
Invoice	Lloydminster AB T9V 3A2		
ľ			

Branch								
LLOYDMINSTER								
Date	Time				Page			
02/28/24	23:	30:23	(B)		08			
Account No	Phone No			Inv N	0			
INTER01	780	875447	71	S79	9333			
Ship Via		Purchase	Order					
		019						
	•	Sales	person					
				JAF				

DESCRIPTION OF WORK & PARTS

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS Fold 030230 4130 1RW6175RTKD036406 04/30/21 2000 6175R NAZZ CORRAL 6175R PE6068U073023 04/30/23 4000 X INTERNAL CUSTOMER PARTS 3064.90 LABOR 4976.16 250.00 SHOP SUPPLIES INTERNAL TOTAL 8291.06

Terms: Full payment due immediately upon completion of work or service charge on overdue account at the rate of 1.5% per month (18% per annum)
It is understood that this company assumes no responsibility for loss or damage by theft or fire to

machine placed with them for storage, sale, repair, or while field testing.

Signature

[•] I hereby certify the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection, or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto.