

American Tank Solutions, LLC  
7744 Beauxare Garden Road  
Nederland, Texas, 77627  
855-547-2855



Wash Ticket #: 132549  
Date & Time: 09/17/2025 11:52 a.m.  
Delivered By:  
Payment: Account  
PO #: None

### Tank Container Cleanliness Certificate

**Customer Information:**

HPC Industrial Port Arthur/Clean Harbors  
16019 Sabine Consolidated Rd  
Beaumont, TX, 77705  
Customer No.: 608

**Contact Information**

Office:  
Cell:

**Unit Information**

Unit Type: Vac Truck  
Tractor ID:  
Unit #: 917163

Manifest/BOL#:

Compartments: 1

Vessel Pressure: 0

**Unit Compartment Summary**

Compartment #	Last Contained Material	Gallons	HAZ / NH
1	Lubricating Oil	0	Non Haz
Total Gallons:		0	

**Unit Services Summary**

Item #	Service Item	Quantity	Units
10133	Vac Truck Clean	1	Each
10141	Energy and EIS Recovery Fee	1	Each

Service Initiated: 10/08/2025 08:00

Service Completed 10/08/2025 09:00

Comments:

Waste Heel:

Product Heel:

Gallons

Containers

A thorough visual examination has been carried out and the interior of the tank, valves and fitting are free of contamination, corrosion, previous cargo, odor and pitting. The tanks are clean and dry.

Remarks:

THE REPORT IS BASED SOLELY UPON A VISUAL EXAMINATION OF THE TANK AND THE EXAMINATION OF DOCUMENTATION PROVIDED BY OTHERS. THE SURVEYOR ACCEPTS NO LIABILITY FOR ANY CONDITIONS THAT ARE NOT APPARENT DURING A NORMAL VISUAL INSPECTION OR THAT MAY BE THE RESULT OF INACCURATE INFORMATION PROVIDED IN DOCUMENTS UPON WHICH THE SURVEYOR MUST RELY. \* SUBJECT ONLY TO CLEANLINESS OF THE TANK INTERIOR, VALVES AND FITTINGS

Approval: Banks

TTW Approval Signature/Date