

Texas Tank Works, LLC.

7744 Beauxare Garden Road
Nederland, Texas 77627
855-547-2855

**Wash Ticket #: 30265**

Date&Time: 3/28/2025 11:11

Delivered By:

Payment: Account

PO #: W250024192

Tank Container Cleanliness Certificate**Customer Information:**

HPC Industrial Port Arthur/Clean Harbors
16019 Sabine Consolidated Rd

Beaumont, Texas 77705

Customer No.: 608 /

Contact Information:

Office:

Cell:

Unit Information:

Unit Type: Vac Truck

Tractor ID:

Trailer ID: 917166

Manifest/BOL#:**Compartments: 1****Vessel Pressure: 0****Unit Compartment Summay**

<u>Compartment #</u>	<u>Last Contained Material</u>	<u>Gallons</u>	<u>HAZ / NH</u>
1	HYDROGEN SULFIDE	0.0	Haz

Total Gallons: 0.0

Unit Services Summay

<u>Item #</u>	<u>Service Item</u>	<u>Quantity</u>	<u>Units</u>
1	Vac Truck Clean	1.0	Each
2	HAZ Heel Management/Repackaging Surcharge	55.0	Each
3	Energy and EIS Recovery Fee	1.0	Each

Revenue Type: Waste

Service Initiated:

Service Completed

3:30PM
5:00PM

Gallons **Containers****Waste Heel:** 0.0 0.0**Product Heel:** 0.0 0.0**Comments:** New Tanker Work Order

A through visual examination has been carried out and the interior of the tank, valves and fitting are free of contamination, corrosion, previous cargo, odor and pitting. The tanks is clean and dry.

Remarks:

THE REPORT IS BASED SOLELY UPON A VISUAL EXAMINATION OF THE TANK AND THE EXAMINATION OF DOCUMENTATION PROVIDED BY OTHERS. THE SURVEYOR ACCEPTS NO LIABILITY FOR ANY CONDITIONS THAT ARE NOT APPARENT DURING A NORMAL VISUAL INSPECTION OR THAT MAY BE THE RESULT OF INACCURATE INFORMATION PROVIDED IN DOCUMENTS UPON WHICH THE SURVEYOR MUST RELY.

* SUBJECT ONLY TO CLEANLINESS OF THE TANK INTERIOR, VALVES AND FITTINGS

Approved By:

Federico