

Ship to:	Pitre Trade
Invoice to:	INTERNAL CUSTOMER
	INTERNAL CUSTOMER
	INTERNAL W/O AB T5S 2L7

Branch FALHER		*REPRINT*	
Date 06/13/24	Time 23:05:48 (B)	Page 01	
Account No. INTER01	Phone No.	Invoice No. W21956	
Ship Via		Purchase Order	
		Salesperson TRM	

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
248059BB	JOHN DEERE 9870 ST	2954	1H09870SHB0741624	
	9870 STS		RG6135L024746	

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 16070 NA 06/12/24 06/12/24

Basic Inspection

CORRECTION:

*Perform a basic inspection & service.

- Changed engine oil and filter.
- Changed both engine air filters.
- Changed both fuel filters.
- Changed 4 hydraulic filters.
- Changed both cab filters.
- Aired up the pickup header airbags.

 -Inspection results below:

- Holes in the feeder house transition plate.
- Feeder house floor is almost worn through.
- Feeder house conveyor chain wear strips are worn.
- Rotor 2nd top sheet has holes.
- It has 2 sunny brock concaves and a large wire for the 3rd.
- Engine oil drain hose is cracked in the middle.
- Two speed rotor gear case shifter linkage seal is leaking.
- Shoe auger drive shaft bevel gear keys are starting to be loose.
- Mass flow sensor sheet is broken.
- The bubble up gear case dog is worn out so I gave it a

CONTINUED ON PAGE 02

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,

SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Invoice to:

INTERNAL CUSTOMER
INTERNAL CUSTOMER
INTERNAL W/O AB T5S 2L7

Branch			
FALHER			
Date	Time	Page	
06/13/24	23:05:48 (B)	02	
Account No.	Phone No.	Invoice No.	
INTER01		W21956	
Ship Via		Purchase Order	
		Salesperson	
		TRM	

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
248059BB	JOHN DEERE 9870 ST	2954	1H09870SHB0741624		
	9870 STS		RG6135L024746		

- Fire extinguisher needs to be recharged.
- Adjust clean grain/tailing elevator chains.
- There's play in all the seive/chaffer/shaker pan arms bushings.

- Right wheel spindle on pick up header is damaged and bent sideways and already has been welded, would have to replace spindle arm.
- Vertical auger gearcase has play in the bearings.
- Parked in the back yard all locked up.

AH115833	FILTER AIR CAB	1	124.46	124.46
AH128449	HYDRAULIC FILT	3	124.23	372.69
	Hydraulic Filter			
AH212295	AIR FILTER SEC	1	206.68	206.68
AH222225	AIR FILTER PRIM	1	253.40	253.40
AN207368	HYDRAULIC FILT	1	164.40	164.40
	Hydraulic Filter			
DZ112918	Filter Element	1	199.05	199.05
ENV10	ENVIRO CHARGE	36	.10	3.60
ENV100	ENVIRO CHARGE	7	1.25	8.75
H220870	AIR FILTER	1	77.62	77.62
RE539465	PRIM FUEL FILTR	1	158.37	158.37
RE572785	ENG OIL FILTER	1	127.78	127.78
TY26991L	15w40 1L Bulk	36	8.13	292.68
			PARTS	1989.48
			LABOR	1020.25
16001001	SEGMENT TOTAL==>			3009.73

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees.

***** WORK ORDER TOTALS *****
CONTINUED ON PAGE 03

SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



Falher
Box 57, 712 Main Street SE, Falher, AB, T0H 1M0
Tel: 780.837.2267 Fax: 780.837.2085
www.horizonagturf.com

Ship to:

Pitre Trade

Invoice to:

INTERNAL CUSTOMER
INTERNAL CUSTOMER
INTERNAL W/O AB T5S 2L7

Branch			
FALHER			
Date	Time	Page	
06/13/24	23:05:48 (B)	03	
Account No.	Phone No.	Invoice No.	
INTER01		W21956	
Ship Via		Purchase Order	
		Salesperson	
		TRM	

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	
248059BB	JOHN DEERE 9870 ST	2954	1H09870SHB0741624		
	9870 STS		RG6135L024746		
				INTERNAL	CUSTOMER
			PARTS	1989.48	
			LABOR	1020.25	
			AG EQP SUPPLIES	102.02	
			INTERNAL TOTAL	3111.75	

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO