

03896295

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Standards and Inspections
Box 45064 Regent Postal C
Winnipeg, MB, R2C 5C7
1-204-985-0920



Date Inspection Started: 17 DAY, 05 MO., 25 YR.

Date Inspection Completed: 17 DAY, 05 MO., 25 YR.

Inspection Expiry Date: 31 DAY, 05 MO., 26 YR.

Station Number: A0101, Station Name: Van der Velde Tr, City: _____

Mechanic Number: M9515, Mechanic Signature: [Signature], Station Phone Number: 204-225-4244

Vehicle Owner: _____

Address: _____, City: _____, Province: _____, Postal Code: _____, Phone: _____

Pass/Safe Vehicle

Fail/Unsafe Vehicle

Fail/Hazardous

Licence Number: _____, Prov. MB, NSC #: _____, Odometer Reading: _____, Odom. Type: km mi

Vehicle Identification Number: 2M9PESCGG1B017105, Make: [Signature], Model: Deck, Year: 01, Unit #: _____

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ^{GWR} 27216 KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: A <input checked="" type="radio"/> B <input type="radio"/> C <input type="radio"/> D <input type="radio"/> E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining mm</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>19</td> <td>19</td> <td>12.710</td> <td>12.710</td> <td>1</td> <td>1</td> </tr> <tr> <td>2</td> <td>19</td> <td>19</td> <td>12.710</td> <td>12.710</td> <td>1</td> <td>1</td> </tr> <tr> <td>3</td> <td>19</td> <td>19</td> <td>12.710</td> <td>12.76</td> <td>1 1/4</td> <td>1 1/4</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7" style="text-align: center;">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining mm		Drum/Rotor		Stroke		L	R	L	R	L	R	1	19	19	12.710	12.710	1	1	2	19	19	12.710	12.710	1	1	3	19	19	12.710	12.76	1 1/4	1 1/4	4							5							Final Measurement																					
Axle	Lining mm			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	19	19	12.710	12.710	1	1																																																																		
2	19	19	12.710	12.710	1	1																																																																		
3	19	19	12.710	12.76	1 1/4	1 1/4																																																																		
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial mm</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>8</td> <td>8</td> <td>9</td> <td>9</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>10</td> <td>10</td> <td>8</td> <td>4</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td>11</td> <td>8</td> <td>10</td> <td>11</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial mm		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1									2	8	8	9	9	100	100	100	100	3	10	10	8	4	100	100	100	100	4	11	8	10	11	100	100	100	100	5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial mm			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1																																																																								
2	8	8	9	9	100	100	100	100																																																																
3	10	10	8	4	100	100	100	100																																																																
4	11	8	10	11	100	100	100	100																																																																
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: _____

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature _____ Date: _____