



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A332655

Station #: 71533

Station Name: D-CAN AG REPAIR LTD.

Technician #: 88585

Technician Name: Darrell Kraft

Signing Officer #: 89323

Signing Officer Name: Jason Thrun

Customer Details:

Name: 3D LAND CO LTD.

Address: BOX 581, LUSELAND, Saskatchewan, S0L2A0

Inspection Completed Date: 29Apr2026

Inspection Expiry Date: 31Oct2026

Vehicle Details:

VIN: 1XP5DB9X94D829233

Odometer Reading: 28663 km

Year: 2004

Vehicle Make/Model: PETERBILT/HEAVY VEHICLE

Plate: 598EYE

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71533

Station Name: D-CAN AG REPAIR LTD.

Technician #: 88585

Technician Name: Darrell Kraft

Signing Officer #: 89323

Signing Officer Name: Jason Thrun

Customer Details:

Name: 3D LAND CO LTD.

Address: BOX 581, LUSELAND, Saskatchewan, S0L2A0

Vehicle Details:

VIN: 1XP5DB9X94D829233

Odometer Reading: 28663 km

Year: 2004

Vehicle Make/Model: PETERBILT HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	REAR TOP CLEARANCE LIGHT
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 14 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .488 in • Cam Rotation: 98.0 degrees • Brake Stroke: 1.50 in

Wheel2-On : Tire Tread Depth: 15 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .492 in • Cam Rotation: 96.0 degrees • Brake Stroke: 1.50 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 13 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 13 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .680 in • Cam Rotation: 66.0 degrees • Brake Stroke: 1.50 in

Wheel3-On : Tire Tread Depth: 12 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .676 in • Cam Rotation: 68.0 degrees • Brake Stroke: 1.25 in

Wheel4 : Tire Tread Depth: 12 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 12 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 12 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .630 in • Cam Rotation: 76.0 degrees • Brake Stroke: 1.50 in

Wheel3-On : Tire Tread Depth: 12 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: .620 in • Cam Rotation: 80.0 degrees • Brake Stroke: 1.25 in

Wheel4 : Tire Tread Depth: 12 in

Brake(1): No Brake

N/A