



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A318820

Station #: 71709	Station Name: Redhead Equipment
Technician #: 87734	Technician Name: Cale Boehm
Signing Officer #: 92422	Signing Officer Name: Kasey Kohl

Customer Details:	
Name: ELDON AND LORI MARTENS	Address: P.O. BOX 28, RABBIT LAKE, Saskatchewan, S0M2L0

Inspection Completed Date: 09Feb2026	Inspection Expiry Date: 28Feb2027
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 1W1MCFUA17B246204	Hubometer Reading:
Year: 2007	Vehicle Make/Model: WILSON TRAILER/TRAILER
Plate: 763FGP	Jurisdiction: Saskatchewan
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.
--



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71709

Station Name: Redhead Equipment

Technician #: 87734

Technician Name: Cale Boehm

Signing Officer #: 92422

Signing Officer Name: Kasey Kohl

Customer Details:

Name: ELDON AND LORI MARTENS

Address: P.O. BOX 28, RABBIT LAKE, Saskatchewan, S0M2L0

Vehicle Details:

VIN: 1W1MCFUA17B246204

Hubometer Reading:

Year: 2007

Vehicle Make/Model: WILSON TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	RR SIDE MARKER INOP, LISENCE PLATE LAMP OUT
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
		x		Cargo Bodies/Vessels (8)	BOTTOM HOPPER CROSSMEMBER CORRDED THROUGH
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

*Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	RR, RF, LR S-CAM STICKING, CLEVIS PINS SIEZED,
x				Elec Brake System/Components (3.1)	
		x		Wheel Bearings (9)	LR AND RF WHEEL SEALS LEAKING
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	MONITOR SUSPENSION WHERE WASHERS
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13 mm • Brake Drum/Rotor: 16.563 in • Brake Stroke: 41 mm

Wheel3-Off : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 22 mm • Brake Drum/Rotor: 16.503 in • Brake Stroke: 42 mm

Wheel4 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 8 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13 mm • Brake Drum/Rotor: 16.598 in • Brake Stroke: 42 mm

Wheel3-Off : Tire Tread Depth: 7 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 19 mm • Brake Drum/Rotor: 16.552 in • Brake Stroke: 42 mm

Wheel4 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A318820

Inspection Completed Date: 09Feb2026

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km. Failure to do so may result in damage or serious injury.