



Vehicle Standards and Inspection

Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # P269900

Station #: 71603	Station Name: Highliner Holdings Inc
Technician #: 90375	Technician Name: Ben Kendall
Signing Officer #: 89151	Signing Officer Name: Donna Mains

Customer Details:	
Name: Highliner Holdings Inc.	Address: 119 Dean Street, Carievale, Saskatchewan, s0c0p0

Inspection Completed Date: 07Mar2026	Inspection Expiry Date: 31Mar2027
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: DEMWST118	Hubometer Reading:
Year: 2009	Vehicle Make/Model: TRAILER/TRAILER
Plate: 003JCI	Jurisdiction: Saskatchewan
Unit: WS09	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71603

Station Name: Highliner Holdings Inc

Technician #: 90375

Technician Name: Ben Kendall

Signing Officer #: 89151

Signing Officer Name: Donna Mains

Customer Details:

Name: Highliner Holdings Inc.

Address: 119 Dean Street, Carievale, Saskatchewan, s0c0p0

Vehicle Details:

VIN: DEMWST118

Hubometer Reading:

Year: 2009

Vehicle Make/Model: TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	Taillight/Brake light burnt out. Upper marker lamp burnt out, corrected/fixed with new lights and fixed grounds straps.
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
		x		Battery/Wiring Condition (7)	Junction box, corrosion and loose wires.