

SEVERSATILE





PO Box 743, Highway 16 East, Lloydminster SK S9V 1C1 • www.novlanbros.com GST# 10980 4724 RT0001

Phone: (306) 825-6141 • Fax: (306) 825-9896 • Toll Free: 1-877-344-4433

SO # 306784

SERVICE ORDER INTERNAL COPY

Printed

11/27/2025 9:48:56 AM

User

RDS

Job

Type

WANH

Page

Status

Original

Amount

1,014.93

Amount

5,142.11

5,142.11

1,014.93

6,157.04

1.39

-1.39

Customer No

KO0122

Advisor Shop S1

Damond Souster Promised Opened Cashiered

09/29/2025 11:00 PM Tag# 09/29/2025 9:05 AM Location

11/05/2025 4:04 PM PO#

Bus

Odom In 1309

Odom Out 1309

In Service Date 06/07/2021 **Model Number**

Type

WNH

WNH

WNH

Stock No C2463B Color

Home Cell Email

(780) 632-5678 Today

Year Make 2021 NEW HOLLAND Vehicle ID No

7N2045009

Engine

Priority

License

Model CR10.90Z Selling Dealer NOVLAN BROS.

Shp

1

CR10.90Z **Extended Warranty**

Fleet#

Bin

0123

CORE

Request Total

Parts Total

Labor Total

Delivery Date 06/30/2025

CSR

DCS

Tech

Price

1.39

1.39

5,142.11

JAV

Term Cash

Request MISC

Description

INJECTION PUMP FAILED

Labor MISC

Description LABOUR

Part 5802805240R **CORE CHARGE**

C-5802805240R Correction started the combine

Description **REMAN-FUEL INJ PUMP** CORE CHARGE|5802805240R

CORE RETURN

found a noise coming from the high pressure pump

hooked up the EST and checked for faults fault code F-1240-31 hooked up fuel pressure test equipment

went through all tests

relief valve was not popping fuel pressure was out of spec pulled the plungers out of the pump

found one plunger was stuck and found the cap from the pumping unit was split

removed the lines from the pump marked the gear on the pump

replaced the pump

spun the pump to line up the marks installed the gear and the nut reinstalled the bolts and fuel lines bled the air out of the fuel system

started the combine

listened for any kind of weird sounds

pressures now looked removed test equipment engine running quiet as it should

washed off leaked fuel

Request MISC

Labor

MISC

TRAVEL NOT COVERED BY WARRANTY

Description **LABOUR**

Description

CSR Job AKS 2 Type Tech JAV IΑ

Labor Total Request Total

196.90 196.90

Status

Approved

Amount

196.90

INDEBTEDNESS IS ACKNOWLEDGED I THE SUM OF \$_ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS AND ACCESSORIES DESCRIBED IN THIS SERVICE INVOICE AND THE ACCOMPANYING WORK ORDER.







PO Box 743, Highway 16 East, Lloydminster SK S9V 1C1 • www.novlanbros.com GST# 10980 4724 RT0001

Phone: (306) 825-6141 • Fax: (306) 825-9896 • Toll Free: 1-877-344-4433

SO # 306784

WERSATILE

SERVICE ORDER INTERNAL COPY



Page

RDS

User

Printed 11/27/2025 9:48:56 AM

Customer No KO0122

 Advisor
 Damond Souster
 Promised
 09/29/2025 11:00 PM
 Tag#

 Shop
 S1
 Opened
 09/29/2025 9:05 AM
 Location

 Priority
 Cashiered
 11/05/2025 4:04 PM
 PO #

Home Bus
Cell (780) 632-5678 Today
Email

Term Cash
Detail

License Odom In **Odom Out** In Service Date Stock No 1309 1309 06/07/2021 C2463B Year Make Model Model Number Color 2021 NEW HOLLAND CR10.90Z CR10.90Z Selling Dealer **Extended Warranty** Vehicle ID No **Delivery Date** 7N2045009 NOVLAN BROS. 06/30/2025 Engine Fleet #

Pay Type Supplies Labor **Parts** Fees Misc Sublet Env Ded **GST** Total Customer 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 Warranty 0.00 1.014.93 5,142,11 0.00 0.00 0.00 0.00 0.00 307.85 6,464,89 Internal 196.90 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 196.90 Total 1,211.83 5,142.11 0.00 0.00 0.00 0.00 0.00 0.00 307.85 6.661.79

WARRANTY

ACCOUNT DESCRIPTION
L1142 A/R WARRANTY NEW HOLLAND

TYPE CONTROL# 306784

AMOUNT COMMENTS

6464.89

INTERNAL

ACCOUNT P2427 DESCRIPTION

PRODUCT SUPPORT - COMBINE

TYPE CONTROL#

C2463B

AMOUNT COMMENTS

196.90 Travel not covered by warranty, as per Damond.045009 - 2021 NEW HOLLAND CR10.90Z COMBINE