



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A374122

Station #: 70925

Station Name: Keep on Truckin Mechanical

Technician #: 91261

Technician Name: Michael Herle

Signing Officer #: 80601

Signing Officer Name: Cora Manson

Customer Details:

Name: Beamish Farms Ltd

Address: Box 2127, Lloydminster, Saskatchewan, S9V1R6

Inspection Completed Date: 13Oct2026

Inspection Expiry Date: 30Apr2027

Vehicle Details:

VIN: 1XPXD49X5DD188182

Odometer Reading: 65106 km

Year: 2013

Vehicle Make/Model: PETERBILT/HEAVY VEHICLE

Plate: 617LTW

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70925

Station Name: Keep on Truckin Mechanical

Technician #: 91261

Technician Name: Michael Herle

Signing Officer #: 80601

Signing Officer Name: Cora Manson

Customer Details:

Name: Beamish Farms Ltd

Address: Box 2127, Lloydminster, Saskatchewan, S9V1R6

Vehicle Details:

VIN: 1XPXD49X5DD188182

Odometer Reading: 65106 km

Year: 2013

Vehicle Make/Model: PETERBILT HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
		x		Mirrors (8)	LH convex mirror heat not working
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	LH air cleaner lights out
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
		x		Retro Reflective Markings (6)	Rear mud flap reflectors missing
x				Body/Bumpers (8)	
		x		Trailer Hitch (10)	5th wheel needs adjusting
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
		x		Cab Mounts (8)	RH cab shock loose
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
		x		Exhaust/Emission System (1)	Exhaust manifold leak

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 13 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 18.5 mm • Brake Drum/Rotor: 42.32 mm

Wheel2-On : Tire Tread Depth: 13 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 17.8 mm • Brake Drum/Rotor: 41.96 mm

Axle 2-Pass

Wheel1 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 9 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 18.3 mm • Brake Drum/Rotor: 42.32 mm

Wheel3-On : Tire Tread Depth: 10 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 18.1 mm • Brake Drum/Rotor: 42.27 mm

Wheel4 : Tire Tread Depth: 12 mm

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 18 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 18 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 16.9 mm • Brake Drum/Rotor: 41.88 mm

Wheel3-On : Tire Tread Depth: 18 mm

Brake(1): Disc Brake

• Min Brake Lining/Pad: 17.3 mm • Brake Drum/Rotor: 42.13 mm

Wheel4 : Tire Tread Depth: 18 mm

Brake(1): No Brake

N/A