SGI

Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #:	Station Name:
Technician #:	Technician Name:
Signing Officer #.	Signing Officer Name:

Customer Details:

Name: Beamish Farms Ltd

Address: Box 2127, Lloydminster, Saskatchewan, S9V1R6

Vehicle Details:

VIN: 2AEASXBFXRR000265

Hubometer Reading:

Year: 1994

Vehicle Make/Model: ADVANCE TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
		x		Vehicle Identification (5)	No document holder
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	No I.D. light, brake lights not working
x				Reflex Reflectors (6)	
		x		Retro Reflective Markings (6)	Rear reflective strips faded
x				Trailer Hitch (10)	
		x		Attached Equipment (8)	Hose tray not secure
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	#3 lh/rh clevis pins seized, #2 lh brake not returning properly, air tank drain leaking
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 14 mm
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 14 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 18.1 mm • Cam Rotation: 53.0 degrees • Brake Stroke: 35 mm
Wheel3-On : Tire Tread Depth: 13 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 19 mm • Cam Rotation: 44.0 degrees • Brake Stroke: 35 mm
Wheel4 : Tire Tread Depth: 15 mm
Brake(1): No Brake
N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 14 mm
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 14 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 18.6 mm • Cam Rotation: 48.0 degrees • Brake Stroke: 35 mm
Wheel3-On : Tire Tread Depth: 13 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 18.4 mm • Cam Rotation: 51.0 degrees • Brake Stroke: 35 mm
Wheel4 : Tire Tread Depth: 13 mm
Brake(1): No Brake
N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 14 mm
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 14 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 19.2 mm • Cam Rotation: 42.0 degrees • Brake Stroke: 35 mm
Wheel3-On : Tire Tread Depth: 14 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 18.1 mm • Cam Rotation: 54.0 degrees • Brake Stroke: 35 mm

Wheel4 : Tire Tread Depth: 15 mm
Brake(1): No Brake
N/A

PASS - vehicle passes inspection	Decal # A374126	Inspection Completed Date: 05Nov2026