



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A358985

Station #: 72033

Station Name: Fab-All Welding

Technician #: 92457

Technician Name: Austin Walker

Signing Officer #: 89020

Signing Officer Name: Blaine Klein

Customer Details:

Name: LORNE HOFER

Address: BOX 746, WILKIE, Saskatchewan, S0K4W0

Inspection Completed Date: 03Sep2026

Inspection Expiry Date: 30Sep2027

Vehicle Details:

VIN: 1W14302A6D2260837

Hubometer Reading:

Year: 2013

Vehicle Make/Model: WILSON TRAILER/TRAILER

Plate:

Jurisdiction:

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 72033

Station Name: Fab-All Welding

Technician #: 92457

Technician Name: Austin Walker

Signing Officer #: 89020

Signing Officer Name: Blaine Klein

Customer Details:

Name: LORNE HOFER

Address: BOX 746, WILKIE, Saskatchewan, S0K4W0

Vehicle Details:

VIN: 1W14302A6D2260837

Hubometer Reading:

Year: 2013

Vehicle Make/Model: WILSON TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
			x	Mud Flaps/Fenders (8)	-BOTH FENDERS IN FRONT OF AXLE 1 CRACKED RIGHT ONE LOOSE AS WELL-REPLACE REMOVAL MIGHT ALSO BE AN OPTION
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
		x		Tires/Wheels (9)	-AXLE 1 RIGHT OUTER TIRE CUPPING PRETTY BAD
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 5/16 in

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 5/16 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 17 mm • Brake Drum/Rotor: 16.515 in • Brake Stroke: 1 1/2 in

Wheel3-Off : Tire Tread Depth: 11/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 17 mm • Brake Drum/Rotor: 16.515 in • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 11/32 in

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 11/32 in

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 5/16 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Brake Drum/Rotor: 16.525 in • Brake Stroke: 1 1/4 in

Wheel3-Off : Tire Tread Depth: 3/8 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Brake Drum/Rotor: 16.525 in • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 11/32 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 21/32 in

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 21/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Brake Drum/Rotor: 16.525 in • Brake Stroke: 1 1/4 in

Wheel3-Off : Tire Tread Depth: 21/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Brake Drum/Rotor: 16.525 in • Brake Stroke: 1 3/8 in

Wheel4 : Tire Tread Depth: 5/8 in

Brake(1): No Brake

N/A

Axle 4-Pass

Wheel1 : Tire Tread Depth: 21/32 in

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 21/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Brake Drum/Rotor: 16.525 in • Brake Stroke: 1 1/4 in

Wheel3-Off : Tire Tread Depth: 21/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Brake Drum/Rotor: 16.525 in • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 5/8 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection	Decal # A358985	Inspection Completed Date: 03Sep2026
----------------------------------	-----------------	--------------------------------------

One or more wheels were removed for inspection. Warning: Wheel nuts MUST be RE-TORQUED within 100-150 km. Failure to do so may result in damage or serious injury.
