

Date Inspection Started DAY 03 MO. 09 YR. 25	Station Number A55219	Station Name 4675760 M6120	City 204 351 4123
Date Inspection Completed DAY 03 MO. 09 YR. 25	Mechanic Number M44110	Mechanic Signature 5168059 M6120	Station Phone Number
Inspection Expiry Date DAY 30 MO. 09 YR. 26	Vehicle Owner	Address	City Province Postal Code Phone
☒ Pass/Safe Vehicle ☐ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number C10J74162	Prov. MA NSC # 78692491	Odometer Reading 389622
	Vehicle Identification Number 445T1C120E94M9671552	Make VW	Model Year 00 Unit #
	☐ Confirmed legible Vehicle Identification Number on vehicle		

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

GVWR 7413100 KGS ☒ Truck ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>3/8</td><td>5/8</td><td>16.5</td><td>16.5</td><td>1.2</td><td>1.2</td></tr><tr><td>2</td><td>5/8</td><td>3/8</td><td>16.5</td><td>16.5</td><td>1.2</td><td>1.2</td></tr><tr><td>3</td><td>5/8</td><td>5/8</td><td>16.5</td><td>16.5</td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	3/8	5/8	16.5	16.5	1.2	1.2	2	5/8	3/8	16.5	16.5	1.2	1.2	3	5/8	5/8	16.5	16.5			4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	3/8	5/8	16.5	16.5	1.2	1.2																																																																		
2	5/8	3/8	16.5	16.5	1.2	1.2																																																																		
3	5/8	5/8	16.5	16.5																																																																				
4																																																																								
5																																																																								
Final Measurement																																																																								
		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"><thead><tr><th rowspan="3">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>14</td><td>13</td><td></td><td></td><td>100</td><td>100</td><td></td><td></td></tr><tr><td>2</td><td>12</td><td>19</td><td>19</td><td>20</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>3</td><td>16</td><td>19</td><td>16</td><td>16</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	14	13			100	100			2	12	19	19	20	100	100	100	100	3	16	19	16	16	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	14	13			100	100																																																																		
2	12	19	19	20	100	100	100	100																																																																
3	16	19	16	16	100	100	100	100																																																																
4																																																																								
5																																																																								
		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: