

04064321

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Out
Winnipeg, MB, R2C 6C7
1-204-985-0920

Manitoba

C021530

Date Inspection Started DAY: 09 MO: 02 YR: 2008	Station Number A3073	Station Name Can Am Colony	City Minnedota
Date Inspection Completed DAY: 18 MO: 02 YR: 2008	Mechanic Number M7995	Mechanic Signature [Signature]	Station Phone Number 776-2081
Inspection Expiry Date DAY: 28 MO: 02 YR: 2009	Vehicle Owner Can American Corrugated Ltd	Address Rox 7 Margaret MB R0K 1S0	
Licence Number TF6004		Prov. MB	NSC #
Vehicle Identification Number 2LDPF323656041169		Make Ford	Model Deck
Confirmed legible Vehicle Identification Number on vehicle		Year 2005	Unit #
Odometer Reading		Odom. Type km	mi

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 14(B) L2 Brake pad spring broken. 20(A) ABS light does not go out. 20(B) wiring at sensor loose.
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) 1(H) LH rear side marker light not working. 3(C) Bunch of reflective tape peeling.
X	X	Section 7 - Electrical System: Defects (if any) 1(B) rear trailer cord insulation cracked.
X	X	Section 8 - Body: Defects (if any) 1(B) hole in Deck 1(D) front cross member rotted through. 2(A) RH Rear Sander Support Broken.
X	X	Section 9 - Tire & Wheel: Defects (if any) 1(B) L11 + RH tire tread 5(C) R3, R2, L2 wheel seals level 2 leak.
X	X	Section 10 - Coupling Devices: Defects (if any) 1(C) Rear 5th wheel jaws loose.

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	13	3	9	13	110	110	110	110
2	15	14	15		110	110	110	110
3	11	11	11		110	110	110	110
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date:

2373040