

Date Inspection Started  
DAY: 10 MO: 02 YR: 20

Date Inspection Completed  
DAY: 18 MO: 02 YR: 20

Date Expiry Date  
DAY: 28 MO: 02 YR: 27

Station Number  
A3073

Mechanic Number  
M7995

Vehicle Owner  
Can American Ltd

Address  
Box 9

City  
Margaret

Province  
MB

Postal Code  
R0K 1S0

Phone

Station Name  
Can Am Colony

Mechanic Signature  
[Signature]

Station Phone Number  
776-2081

☐ Pass/Safe Vehicle

☒ Fail/Unsafe Vehicle

☐ Fail/Hazardous

Licence Number  
TF6005

Vehicle Identification Number  
24DPF2820X6032043

Confirmed legible Vehicle Identification Number on vehicle

Prov.  
MB

NSC #

Odometer Reading

Odom. Type  
km

Make  
Ford

Model  
Deck

Year  
1999

Unit #

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR: KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

| P | R | Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section   |
|---|---|---------------------------------------------------------------------------------------------------------------------------------------------|
| X |   | Section 1 - Power Train: Defects (if any)                                                                                                   |
| X |   | Section 2 Suspension: Defects (if any)                                                                                                      |
| X | X | Section 3 - Brake Systems: 3H 3A<br>Defects (if any) Circle Brake Type<br>20(A) ABS light not labeled.                                      |
| X |   | Section 4 - Steering: Defects (if any)                                                                                                      |
| X |   | Section 5 - Instruments & Auxiliary Equipment: Defects (if any)                                                                             |
| X | X | Section 6 - Lamps: Defects (if any)<br>1(G) LH tail light not working<br>1(F) LH Rear turn not working<br>3(C) some reflective tape peeling |
| X |   | Section 7 - Electrical System: Defects (if any)                                                                                             |
| X |   | Section 8 - Body: Defects (if any)<br>6(C) 2x4 crossmember rotting at front crossmember<br>10(L) left side rail has holes                   |
| X | X | Section 9 - Tire & Wheel: Defects (if any)<br>1(C) L1 tire tread<br>5(C) L1 wheel seal leak<br>5(D) R2 hub oil contaminated                 |
| X |   | Section 10 - Coupling Devices: Defects (if any)                                                                                             |

| Axle | Tread Depth |    |           |    | Air Pressure |     |           |     |
|------|-------------|----|-----------|----|--------------|-----|-----------|-----|
|      | Initial     |    | Corrected |    | Initial      |     | Corrected |     |
|      | L           | R  | L         | R  | L            | R   | L         | R   |
| 1    | 3/4         | 13 | 13        | 13 | 110          | 110 | 110       | 110 |
| 2    | 12          | 9  | 6         |    | 110          | 110 | 110       | 110 |
| 3    |             |    |           |    |              |     |           |     |
| 4    |             |    |           |    |              |     |           |     |
| 5    |             |    |           |    |              |     |           |     |

- THIS INSPECTION IS NOT A WARRANTY -  
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date:

