



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

A329090

Station #: 71539	Station Name: 101297580 Saskatchewan Ltd
Technician #: 86958	Technician Name: Jesse Hobman
Signing Officer #: 90477	Signing Officer Name: Sarah Barczai

Customer Details:	
Name: KIM BERTORIA	Address: BOX 24, BALDWINTON, Saskatchewan, S0M0B0

Inspection Completed Date: 01Jun2026	Inspection Expiry Date: 31Dec2026
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 2XKADR9X2PM929783	Odometer Reading: 232257 km
Year: 1993	Vehicle Make/Model: KENWORTH/HEAVY VEHICLE
Plate:	Jurisdiction:
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.
--



Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71539

Station Name: 101297580 Saskatchewan Ltd

Technician #: 86958

Technician Name: Jesse Hobman

Signing Officer #: 90477

Signing Officer Name: Sarah Barczai

Customer Details:

Name: KIM BERTORIA

Address: BOX 24, BALDWINTON, Saskatchewan, S0M0B0

Vehicle Details:

VIN: 2XKADR9X2PM929783

Odometer Reading: 232257 km

Year: 1993

Vehicle Make/Model: KENWORTH HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 15/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 80 degrees • Brake Stroke: 1.5 in

Wheel2-On : Tire Tread Depth: 14/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 75 degrees • Brake Stroke: 1.5 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 24/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 25/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 80 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 24/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 78 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 23/32 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 21/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 20/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 35 degrees • Brake Stroke: 1.5 in

Wheel3-On : Tire Tread Depth: 20/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 25 degrees • Brake Stroke: 1.5 in

Wheel4 : Tire Tread Depth: 19/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection	Decal # A329090	Inspection Completed Date: 01Jun2026
----------------------------------	-----------------	--------------------------------------