

04056858

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Office
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

C140951

Date Inspection Started DAY: 02 MO: 09 YR: 26	Station Number A11889	Station Name SALYN'S REPAIR	City Winnipeg
Date Inspection Completed DAY: 02 MO: 09 YR: 26	Mechanic Number M62716	Mechanic Signature [Signature]	Station Phone Number
Inspection Expiry Date DAY: 30 MO: 09 YR: 27	Vehicle Owner Bob Rostesky		
	Address Reservoir MB R0S1ND		
	City	Province	Postal Code
	Phone		

☒ Pass/Safe Vehicle ☐ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number KAL1232	Prov. MB	NSC #	Odometer Reading 315983	Odom. Type ☒ km ☐ mi
	Vehicle Identification Number 3HISDL5MR5DN2100387	Make IHC	Model Pro 3.0	Year 2013	Unit #
	☒ Confirmed legible Vehicle Identification Number on vehicle				

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
☒		Section 1 - Power Train: Defects (if any)
☒		Section 2 Suspension: Defects (if any)
☒		Section 3 - Brake Systems: 3H <u>3A</u> Defects (if any) Circle Brake Type
☒		Section 4 - Steering: Defects (if any)
☒		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
☒		Section 6 - Lamps: Defects (if any)
☒		Section 7 - Electrical System: Defects (if any)
☒		Section 8 - Body: Defects (if any)
☒		Section 9 - Tire & Wheel: Defects (if any)
		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1		12 12			100	100		
2	21	21	21	21	100	100	100	100
3	21	21	21	21	100	100	100	100
4								
5								

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	736	670	16.515	16.513	1/2	1/2
2	553	491	16.542	16.528	1/2	1/2
3	778	611	16.597	16.522	1/2	1/2
4						
5						
Final Measurement						

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: _____

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature _____ Date: _____

