04025715 **PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE**

Manitoba

Vehicle Standards and Insp
Box 45064 Regent Postal Out
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

C029832

Date Inspection Started	11 (DAY)	01 (MO.)	26 (YR.)
Date Inspection Completed	24 (DAY)	01 (MO.)	26 (YR.)
Inspection Expiry Date	31 (DAY)	01 (MO.)	27 (YR.)

Station Number: A5293 — Station Name: JAZ MECHANICAL LTD — City:

Mechanic Number: M3970 — Mechanic Signature: [signature] — Station Phone Number: 204 9976075

Vehicle Owner: BOB PERFANICK TRUCKING INC.

Address: — City: — Province: — Postal Code: — Phone:

- [X] Pass/Safe Vehicle
- [X] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: SR95216 — Prov.: MB — NSC #: — Odometer Reading: — Odom. Type: [ ] km [ ] mi

Vehicle Identification Number: 2A9073020 5A003916 — Make: ARNES — Model: END DUMP — Year: 2005 — Unit #: J41

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR KGS ___Truck Tractor ___Trailer X Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X	X	**Section 3 - Brake Systems:** 3H (3A) Circle Brake Type Defects (if any) 15F- L/R/A, R/R/A WHEEL SEAL LEVEL 2 LEAK 16C- R/F/A CLEVIS PIN BINDING 16C- UNSIZED ALL CLEVIS PIN 16H- SET BRAKES
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any) 1C- RAISED TAIL LIGHTS ON DUMP BOX
X		**Section 7 - Electrical System:** Defects (if any)
X	X	**Section 8 - Body:** Defects (if any) 5B- CRACKS INSIDE REAR OF BOX
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	5/8	1/2	16.595	16.559	1 1/8	1 1/8
2	5/8	9/16	16.561	16.597	1 1/8	1 1/8
3						
4						
5						
	Final Measurement					

32	Tread Depth Initial L		Initial R		Corrected L		Corrected R		Air Pressure Initial L		Initial R		Corrected L		Corrected R	
Axle																
1	7	7	7	7					100	100	100	100				
2	8	8	8	8					100	100	100	100				
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: [signature] Signature — Date: 01/11/26

Ce document peut être obtenu en français sur demande.

FVS0022-01-(R-09/15)

PRESENT THIS COPY WHEN REGISTERING VEHICLE

38 MCC ©2023. All rights reserved. — 9355