

04074797

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Safety Box 45084 Regent Postal Dr Winnipeg, MB R2C 5C7 T: 204 985-0920



0069394

Date Inspection Started: 28/02/26
 Date Inspection Completed: 01/03/26
 Inspection Expiry Date: 31/03/27

Station Number: A5293 Station Name: JAZ MECHANICAL LTD L
 Mechanic Number: M39710 Mechanic Signature: [Signature] Station Phone Number: 204 997 6075

Vehicle Owner: BOB POZANICK TRUCKING INC.
 Address: _____ City: _____ Province: _____ Postal Code: _____ Phone: _____

License Number: CJK0968 Prov: MB NSC #: 9569419 Odometer Reading: 711249 Odom. Type: km mi

Vehicle Identification Number: 4V14N1C9EM6D1N131177V Make: VOLVO Model: DUMP Year: 2013 Unit #: 25

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

X Truck 24500 KGS _____ Truck Tractor _____ Trailer _____ Semi-Trailer _____ Bus _____ School Bus _____ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																																	
X		Section 1 - Power Train: Defects (if any)																																																																																	
X		Section 2 Suspension: Defects (if any)																																																																																	
X	X	Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type 15E- R13A BRAKE DRUM BELOW SPEC 16E- STEER AXLE SLACK ADJ'S NOT HOLDING ADJUSTMENT 16E- L1RA, R13A SLACK ADJ NOT HOLDING ADJUSTMENT Brake Inspection Type: (A) B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																																	
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>5/8</td> <td>5/8</td> <td>16.590</td> <td>16.555</td> <td>1"</td> <td>1"</td> </tr> <tr> <td>2</td> <td>11/16</td> <td>5/8</td> <td>16.516</td> <td>16.505</td> <td>1 1/8</td> <td>1 1/8</td> </tr> <tr> <td>3</td> <td>1/2</td> <td>1/2</td> <td>16.565</td> <td>16.552</td> <td>1 1/8</td> <td>1 1/8</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	5/8	5/8	16.590	16.555	1"	1"	2	11/16	5/8	16.516	16.505	1 1/8	1 1/8	3	1/2	1/2	16.565	16.552	1 1/8	1 1/8	4							5																																							
Axle	Lining			Drum/Rotor		Stroke																																																																													
	L	R	L	R	L	R																																																																													
1	5/8	5/8	16.590	16.555	1"	1"																																																																													
2	11/16	5/8	16.516	16.505	1 1/8	1 1/8																																																																													
3	1/2	1/2	16.565	16.552	1 1/8	1 1/8																																																																													
4																																																																																			
5																																																																																			
X		Section 4 - Steering: Defects (if any)																																																																																	
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																	
X		Section 6 - Lamps: Defects (if any)																																																																																	
X	X	Section 7 - Electrical System: Defects (if any) 1A- LOOSE WIRING ON 1ST AXLE UNDER BOX																																																																																	
X		Section 8 - Body: Defects (if any)																																																																																	
X		Section 9 - Tire & Wheel: Defects (if any)																																																																																	
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>32</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>1</td> <td>16</td> <td>16</td> <td></td> <td></td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>11</td> <td>10</td> <td>11</td> <td>11</td> <td>100</td> <td>100</td> <td>160</td> <td>100</td> </tr> <tr> <td>3</td> <td>14</td> <td>14</td> <td>14</td> <td>14</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	32										1	16	16			100	100			2	11	10	11	11	100	100	160	100	3	14	14	14	14	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																														
	Initial		Corrected		Initial		Corrected																																																																												
	L	R	L	R	L	R	L	R																																																																											
32																																																																																			
1	16	16			100	100																																																																													
2	11	10	11	11	100	100	160	100																																																																											
3	14	14	14	14	100	100	100	100																																																																											
4																																																																																			
5																																																																																			
X		Section 10 - Coupling Devices: Defects (if any)																																																																																	

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.
Vehicle received without repairs by: [Signature] Date: FEB 28, 2016