

04065641

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Safety Box 45064 Regent Postal Office Winnipeg, MB, R2C 5C7 1-204-985-0920



Date Inspection Started: 02 DAY, 02 MO, 216 YR
 Date Inspection Completed: 04 DAY, 02 MO, 216 YR
 Inspection Expiry Date: 218 DAY, 02 MO, 217 YR

Station Number: A5293 JAZ MECHANICAL LTD W
 Station Name: JAZ MECHANICAL LTD W
 City: W
 Mechanic Number: M3970
 Mechanic Signature: [Signature]
 Station Phone Number: 204 9976075

Vehicle Owner: BOB PERFANICK TRUCKING INC.
 Address: _____ City: _____ Province: _____ Postal Code: _____ Phone: _____

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Licence Number: ADJ2103 Prov: MB NSC #: 9569419 Odometer Reading: 73141 Odom. Type: km mi

Vehicle Identification Number: 2FVYD1X14B1QMV399381 Make: FIA Model: DUMP Year: 1991 Unit #: 76

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ^{GWR} 235100 KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																																
X		Section 1 - Power Train: Defects (if any)																																																																																
X		Section 2 Suspension: Defects (if any)																																																																																
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any): 16H- SET ALL BRAKES Circle Brake Type: 3A Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																																
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>7/16</td> <td>1/2</td> <td>16572</td> <td>16553</td> <td>1"</td> <td>1"</td> </tr> <tr> <td>2</td> <td>11/16</td> <td>11/16</td> <td>16556</td> <td>16580</td> <td>1 1/8</td> <td>1 1/8</td> </tr> <tr> <td>3</td> <td>11/16</td> <td>11/16</td> <td>16563</td> <td>16582</td> <td>1 1/8</td> <td>1 1/8</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7" style="text-align: center;">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	7/16	1/2	16572	16553	1"	1"	2	11/16	11/16	16556	16580	1 1/8	1 1/8	3	11/16	11/16	16563	16582	1 1/8	1 1/8	4							5							Final Measurement																															
Axle	Lining			Drum/Rotor		Stroke																																																																												
	L	R	L	R	L	R																																																																												
1	7/16	1/2	16572	16553	1"	1"																																																																												
2	11/16	11/16	16556	16580	1 1/8	1 1/8																																																																												
3	11/16	11/16	16563	16582	1 1/8	1 1/8																																																																												
4																																																																																		
5																																																																																		
Final Measurement																																																																																		
X		Section 4 - Steering: Defects (if any)																																																																																
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																
X		Section 6 - Lamps: Defects (if any)																																																																																
X	X	Section 7 - Electrical System: Defects (if any): 2A- CORROSION ON BATTERY TERMINALS																																																																																
X		Section 8 - Body: Defects (if any)																																																																																
X		Section 9 - Tire & Wheel: Defects (if any)																																																																																
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <td></td> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>32</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>1</td> <td>14</td> <td>14</td> <td></td> <td></td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>11</td> <td>11</td> <td>12</td> <td>12</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>13</td> <td>13</td> <td>15</td> <td>15</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	32									1	14	14			100	100			2	11	11	12	12	100	100	100	100	3	13	13	15	15	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																													
	Initial		Corrected		Initial		Corrected																																																																											
	L	R	L	R	L	R	L	R																																																																										
32																																																																																		
1	14	14			100	100																																																																												
2	11	11	12	12	100	100	100	100																																																																										
3	13	13	15	15	100	100	100	100																																																																										
4																																																																																		
5																																																																																		
X		Section 10 - Coupling Devices: Defects (if any)																																																																																

- THIS INSPECTION IS NOT A WARRANTY - This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature _____ Date: _____