

03949278

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

A07-15

Vehicle Standards and Safety
Box 4104, Winnipeg, R4G 1G7
204-985-0077

Manitoba

A902361

Date Inspection Started: 21 04 25
Date Inspection Completed: 21 04 25
Inspection Expiry Date: 31 04 26

Station Number: A0233
Mechanic Number: M9419
Station Name: PENNER INTL. STEINBACH
Mechanic Signature: [Signature]
Station Phone Number: 204-346-5185

Vehicle Owner: PENNER INTERNATIONAL INC.
Address: 20 PTH 12 N STEINBACH MB
City: STEINBACH
Province: MB
Postal Code: R5G 1B7
Phone: 204-346-5185

License Number: SR94137
Vehicle Identification Number: 1GR1A06251AT1555204
Year: 10
Model: VAN
Unit: 8602P

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

☒ Confirmed to legal vehicle identification number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☒ Tractor ☐ Trailer ☐ Semi-Trailer ☒ Bus ☐ School Bus ☐ Coach Bus ☐

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark 'X' under 'R' when item Rejected 'XX' under 'R' when item Hazardous 'X' under 'P' when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any)

Section 2 Suspension: Defects (if any) 7C) BOTH REAR SHOCKS LEAK
5B) BOTH FRONT AIR BAGS HAVE CORDS SHOWING

Section 3 - Brake Systems: 3H 3A
Defects (if any) Circle Brake Type
14B) RIGHT REAR BRAKE CHAMBER SPRING
14G) LEFT FRONT BRAKE CHAMBER SPRING
15C) BOTH FRONT BRAKE SHOE THICKNESS

Brake Inspection Type: A B C D E Circle appropriate letter for internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	87	87	16.538	16.538	1.5	1.5
2	86	84	16.502	16.502	1.5	1.5
3						
4						
5						

Final Measurement:

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any)

Section 7 - Electrical Systems: Defects (if any)

Section 8 - Body: Defects (if any)

Section 9 - Tire & Wheel: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	10	6	6		93	93	95	95
2	8	7	7	10	87	87	95	95
3								
4								
5								

Section 10 - Coupling Devices: Defects (if any)

THIS INSPECTION IS NOT A WARRANTY

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____

Signature: _____

VISED-01 (08/13)

PRESENT THIS COPY WHEN REGISTERING VEHICLE

Ce document doit être retourné en 14 jours à la SAAQ