

03635306

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba A07-2

Vehicle Standards and Inspection
Box 45064, Winnipeg, MB, R2G 5C7
1-204-985-0979Manitoba
A719280

Date Inspection Started: 21 04 23
Date Inspection Completed: 21 04 23
Inspection Expiry Date: 30 04 24

Station Name: Bell Trailer Sales Winnipeg
Mechanic Signature: [Signature]
Mechanic Number: [Redacted]

☒ Pass/Safe Vehicle
☐ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: [Redacted] Prov. MB NSC # [Redacted]
Vehicle Identification Number: 1DW1A53294B650208 Make: Stou Model: Van Year: 2004 Unit #: 5V 357
☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X	X	Section 2 - Suspension: Defects (if any) 5. R/R + L/R air bags cracked																																																																						
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>11/16</td> <td>11/16</td> <td>16.57</td> <td>16.57</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>2</td> <td>5/8</td> <td>5/8</td> <td>16.58</td> <td>16.58</td> <td>1 1/2</td> <td>1 1/2</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	11/16	11/16	16.57	16.57	1 1/2	1 1/2	2	5/8	5/8	16.58	16.58	1 1/2	1 1/2	3							4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	11/16	11/16	16.57	16.57	1 1/2	1 1/2																																																																		
2	5/8	5/8	16.58	16.58	1 1/2	1 1/2																																																																		
3																																																																								
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X	X	Section 8 - Body: Defects (if any) 7. Interior rivets missing R/S + L/S wall																																																																						
X	X	Section 9 - Tire & Wheel: Defects (if any) 5. R/F + L/R wheel seal leak level 3																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>13/12</td> <td>10/10</td> <td></td> <td></td> <td>100/100</td> <td>100/100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>8/11</td> <td>12/10</td> <td></td> <td></td> <td>100/100</td> <td>100/100</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	13/12	10/10			100/100	100/100			2	8/11	12/10			100/100	100/100			3									4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	13/12	10/10			100/100	100/100																																																																		
2	8/11	12/10			100/100	100/100																																																																		
3																																																																								
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

FVS0022-01-(R-09/15)

Ce document peut être obtenu en français sur demande.

COPY IN CAR - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION