

04000086

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

A97-21

Vehicle Standards and Inspection
Box 40044, Regent Postal Outlet
Winnipeg, MB, R2C 9C7
1-204-986-0920

Manitoba

A985562

Date Inspection Started 05/11/25
Date Inspection Completed 05/11/25
Inspection Expiry Date 30/11/26

Station Number A10293
Mechanic Number M11041419

PENNER INTL. STEINDACH

Station Name

City

Cyclist

Mechanic Signature

204-346-5185
Station Phone Number

Vehicle Owner C.A.T. TRANSPORT / PENNER INTERNATIONAL INC.

20 PTH 12N STEINDACH

MB

R5G1B7

204-346-5185

Address

City

Province

Postal Code

Phone

- ☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number SK19457

Prov. MB

NSC #

MB9021893

Odometer Reading

Odom. Type km mi

Vehicle Identification Number

11GRIA0627AT555202

Make

G-D

Model

VAN

Year

10

Unit #

85279

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Truck ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any)

Section 2 Suspension: Defects (if any) ADVISE - SUSPENSION DUMP VALVE SEIZED

Section 3 - Brake Systems: 3H 3A

Defects (if any) Circle Brake Type

2000 ABS LIGHT NOT COMING ON

1300 EMERGENCY AND SERVICE BRAKE

HANDS AT REAR

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any) 100 RIGHT CLEARANCE LIGHT

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any) 2100 MUD FLAP BRACKET

Section 9 - Tire & Wheel: Defects (if any) 9A) LEFT REAR OUTER TIRE INFLATION

40) RIGHT FRONT INNER AND OUTER TIRE INFLATION

Section 10 - Coupling Devices: Defects (if any) 300 PINTLE HITCH SEIZED

Brake Inspection Type: A B C D E

Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						

Axle	Lining		Drum/Botor		Stroke	
	L	R	L	R	L	R
1	5.74	6.18	16.535	16.531	1.25	1.25
2	5.82	6.18	16.517	16.525	1.25	1.25
3						
4						
5						