

03993896

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



A07-4

Vehicle Standards and Insp.
Box 45064 Regent Postal Centre
Winnipeg, MB, R2C 5C7
1-204-985-0930

Manitoba



A971195

Date Inspection Started 1/8 08 25
DAY MO. YR.

Date Inspection Completed 1/8 08 25
DAY MO. YR.

Inspection Expiry Date 3/1 08 26
DAY MO. YR.

Station Number A10121313 Penner Intl. Inc. Steinhilber
City
Mechanic Number M110141419 Cing Gaud
Mechanic Signature
Station Phone Number 204-346-5185

Vehicle Owner Penner International Inc.
Address 20 PTH 12 W Steinhilber MB Postal Code R5G 1B7 Phone 204-346-5185

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number SIR194114 Prov. MB NSC # MB2021893 Odometer Reading Odom. Type ☐ km ☐ mi

Vehicle Identification Number 1UGRPA106121XAT151511719 Make Pontiac Model V6 Year 10 Unit # 8484P

☒ Confirmed legal Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

N/A Section 1 - Power Train: Defects (if any)

X X Section 2 Suspension: Defects (if any) 7C) LF, RR shock's looking

X X Section 3 - Brake Systems: 3H 3A
Defects (if any) 20a) ABS Light Broken
Circle Brake Type

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	<u>806</u>	<u>727</u>	<u>16.541</u>	<u>16.556</u>	<u>1.25</u>	<u>1.25</u>
2	<u>486</u>	<u>748</u>	<u>16.555</u>	<u>16.548</u>	<u>1.25</u>	<u>1.25</u>
3						
4						
5						

Final Measurement

N/A Section 4 - Steering: Defects (if any)

X Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

X Section 6 - Lamps: Defects (if any)

X Section 7 - Electrical System: Defects (if any)

X Section 8 - Body: Defects (if any)

X Section 9 - Tire & Wheel: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	<u>11</u>	<u>11</u>	<u>11</u>	<u>11</u>	<u>89</u>	<u>92</u>	<u>97</u>	<u>93</u>
2	<u>11</u>	<u>7</u>	<u>7</u>	<u>8</u>	<u>93</u>	<u>90</u>	<u>92</u>	<u>89</u>
3								
4								
5								

X Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature

Date:

Ce document peut être obtenu en français sur demande.

FV50022-01-(R-09/15)

PRESENT THIS COPY WHEN REGISTERING VEHICLE

Scanned with

CamScanner