

03993647

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

A07-5

Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-665-0920

Manitoba

A902470

Date Inspection Started DAY: 22 MO: 05 YR: 25	Station Number A01233	Station Name PENNER INTL. STEINBA	City Steinbach
Date Inspection Completed DAY: 22 MO: 05 YR: 25	Mechanic Number M94119	Mechanic Signature <i>[Signature]</i>	Station Phone Number 204-343-5185
Inspection Expiry Date DAY: 31 MO: 05 YR: 26	Vehicle Owner PENNER INTERNATIONAL INC	Address 20 PTH 10N STEINBAH MB	City Steinbach
		Postal Code R5G 1B7	Phone 204-343-5185

☒ Pass/Safe Vehicle	Licence Number SR9415	Prov. MB	NSC # MB9021893	Odometer Reading []	Odom. Type km ☐ ml ☐
☐ Fail/Unsafe Vehicle	Vehicle Identification Number 16RAAD6126A15551810	Make GO	Model VAN	Year 10	Unit # 84859
☐ Fail/Hazardous	☒ Confirmed legible Vehicle Identification Number on vehicle				

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

 Truck ☐ KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
N/A		Section 1 - Power Train: Defects (if any)
X	X	Section 2 Suspension: Defects (if any) 56) RIGHT REAR AIR STRING-CORDS 5 HODWINZ
X	X	Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type 2000 ABS 160) S-CAM EXCESSIVE WEAR-ALL WHEELS 150) ALL BRAKE SHOE THICKNESS
N/A		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) 10) BOTH REAR BRAKE LIGHTS 14) RIGHT FRONT MARKER
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X		Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	7	6	10	9	20	20	25	25
2	10	10	8	9	20	20	25	25
3								
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature

Date: