

B01-12



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A340560

Station #: 71682

Station Name: Garry's Heavy Equipment Repair

Technician #: 88237

Technician Name: Darcy Poole

Signing Officer #: 91324

Signing Officer Name: Renee Day

Customer Details:

Name: 101056947 Sask Ltd. John Warrington

Address: Box 146, Mervin, Saskatchewan, S0M 1Y0

Inspection Completed Date: 29Jul2026

Inspection Expiry Date: 31Jan2027

Vehicle Details:

VIN: 2WKPDDCJ9VK946152

Odometer Reading: 276917 km

Year: 1997

Vehicle Make/Model: WESTERN STAR/HEAVY VEHICLE

Plate: 841-FHB

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71682

Station Name: Garry's Heavy Equipment Repair

Technician #: 88237

Technician Name: Darcy Poole

Signing Officer #: 91324

Signing Officer Name: Renee Day

Customer Details:

Name: 101056947 Sask Ltd. John Warrington

Address: Box 146, Mervin, Saskatchewan, S0M 1Y0

Vehicle Details:

VIN: 2WKPDDCJ9VK946152

Odometer Reading: 276917 km

Year: 1997

Vehicle Make/Model: WESTERN STAR HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
		x		Instrument Lamps (6)	-changed dash bulbs that weren't working
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	-fixed clearance lamp below door on passengerside
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
------	----------	-----------	----------	---------	----------

x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	-changed out left front brake pot hose -changed out right front brake pot hose
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
		x		Engine/Transmission Mounts (1)	-tightened right side transmission mount
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 6 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 44.0 degrees • Brake Stroke: 1 1/4 in

Wheel2-On : Tire Tread Depth: 6 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 43.0 degrees • Brake Stroke: 1 1/4 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 14 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 21.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 32.0 degrees • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 11 mm

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 10 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 32.0 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 8 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 3/4 in • Cam Rotation: 29.0 degrees • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A340560

Inspection Completed Date: 29Jul2026