B01-19

SGI

Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A340555

Station #: 71682

Station Name: Garry's Heavy Equipment Repair

Technician #: 88237

Technician Name: Darcy Poole

Signing Officer #: 91324

Signing Officer Name: Renee Day

Customer Details:

Name: 101056947 Sask ltd. John Warrington

Address: Box 146, Mervin, Saskatchewan, S0M 1Y0

Inspection Completed Date: 27Jul2026

Inspection Expiry Date: 31Jul2027

Vehicle Details:

VIN: 4WWFGB909YN605023

Hubometer Reading:

Year: 2000

Vehicle Make/Model: WILSON TRAILER/TRAILER

Plate: 892 LNB

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

SGI

Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71682

Station Name: Garry's Heavy Equipment Repair

Technician #: 88237

Technician Name: Darcy Poole

Signing Officer #: 91324

Signing Officer Name: Renee Day

Customer Details:

Name: 101056947 Sask ltd. John Warrington

Address: Box 146, Mervin, Saskatchewan, S0M 1Y0

Vehicle Details:

VIN: 4WWFGB909YN605023

Hubometer Reading:

Year: 2000

Vehicle Make/Model: WILSON TRAILER TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	-installed new license plate lamp
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
		x		Cargo Bodies/Vessels (8)	-tightened tank brackets
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	-changed out both glad hand rubbers -installed new abs system -changed out 2nd axle left s-cam, s-cam bushings, brake shoes, and brake drum -installed on 3rd axle right s-cam bushings, brake shoes and brake drum -changed 3rd axle left wheel seal, s-cam bushings, brake shoes, and brake drum -changed out relay valve that was leaking
x				Elec Brake System/Components (3.1)	
		x		Wheel Bearings (9)	-installed new wheel seal and hubcap for 2nd axle right side -installed new wheel seal on 3rd axle right side
		x		Tires/Wheels (9)	-installed new 2nd axle right outside tire -fixed 3rd axle right inside tire
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	-changed out 3rd axle both shocks
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 13 mm
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 13 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 81.0 degrees • Brake Stroke: 1 1/4 in
Wheel3-On : Tire Tread Depth: 11 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 1/2 in • Cam Rotation: 77.0 degrees • Brake Stroke: 1 1/4 in
Wheel4 : Tire Tread Depth: 12 mm
Brake(1): No Brake
N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 12 mm
Brake(1): No Brake
N/A
Wheel2-Off : Tire Tread Depth: 12 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 3/4 in • Brake Drum/Rotor: 16.524 in • Brake Stroke: 1 1/4 in
Wheel3-On : Tire Tread Depth: 10 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 3/8 in • Cam Rotation: 107.0 degrees • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 16 mm
Brake(1): No Brake
N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 12 mm
Brake(1): No Brake
N/A
Wheel2-Off : Tire Tread Depth: 11 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 3/4 in • Brake Drum/Rotor: 16.532 in • Brake Stroke: 1 1/4 in
Wheel3-Off : Tire Tread Depth: 10 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 3/4 in • Brake Drum/Rotor: 16.283 in • Brake Stroke: 1 1/4 in
Wheel4 : Tire Tread Depth: 8 mm
Brake(1): No Brake
N/A

PASS - vehicle passes inspection	Decal # A340555	Inspection Completed Date: 27Jul2026

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km. Failure to do so may result in damage or serious injury.