

MANITOBA

Date Inspection Started: 29 07 24 DAY MO. YR. Station Number: A 1 0 3 6 10001136 MB City: Wesi A891501

Date Inspection Completed: 29 07 24 DAY MO. YR. Mechanic Number: M 5 4 7 0 Mechanic Signature: Peto Pak Station Phone Number: 204-455-6289

Inspection Expiry Date: 31 07 25 DAY MO. YR. Vehicle Owner: GURSHAMINDER SINGH MANN

Address: _____ City: _____ Province: _____ Postal Code: _____ Phone: _____

☒ Pass/Safe Vehicle Licence Number: CHM9494 Prov. MB NSC # _____ Odometer Reading: 719160 Odom. Type: ☒ km ☐ mi

☐ Fail/Unsafe Vehicle Vehicle Identification Number: 1XP1H44947C155770 Make: PETE Model: 579 Year: 12 Unit #: _____

☐ Fail/Hazardous ☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck 416100 GWR KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
☒		Section 1 - Power Train: Defects (if any)																																																																							
☒		Section 2 Suspension: Defects (if any)																																																																							
☒		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																							
		Brake Inspection Type: A B C D <u>E</u> Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>10</td> <td>10</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>new</td> <td>new</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>3</td> <td>8</td> <td>8</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	10	10					2	new	new					3	8	8					4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	10	10																																																																							
2	new	new																																																																							
3	8	8																																																																							
4																																																																									
5																																																																									
Final Measurement																																																																									
☒		Section 4 - Steering: Defects (if any)																																																																							
☒		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
☒		Section 6 - Lamps: Defects (if any)																																																																							
☒		Section 7 - Electrical System: Defects (if any)																																																																							
☒		Section 8 - Body: Defects (if any)																																																																							
☒		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td></td> <td>17 17</td> <td></td> <td></td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>18 18</td> <td>18 18</td> <td></td> <td></td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>19 19</td> <td>19 19</td> <td></td> <td></td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1		17 17			100	100			2	18 18	18 18			100	100	100	100	3	19 19	19 19			100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1		17 17			100	100																																																																			
2	18 18	18 18			100	100	100	100																																																																	
3	19 19	19 19			100	100	100	100																																																																	
4																																																																									
5																																																																									
☒		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature: _____

Date: _____

Ce document peut être obtenu en français sur demande.

FVS0022-01 (R-09/15)

PRESENT THIS COPY WHEN REGISTERING VEHICLE