

04041216

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

Date Inspection Started DAY 13 MO. 09 YR. 26

Date Inspection Completed DAY 14 MO. 09 YR. 26

Inspection Expiry Date DAY 30 MO. 09 YR. 27

Station Number C0152 Station Name ARNOLD BROS TRANSPORT LTD. City 204 257 6666

Mechanic Number M108191 Mechanic Signature Station Phone Number

Vehicle Owner ARNOLD BROS TRANSPORT LTD. 196 CADIMULIERE BLVD WINNIPEG, MANITOBA R2G 0T8

Address City Province Postal Code Phone

Pass/Safe Vehicle

Fail/Unsafe Vehicle

Fail/Hazardous

Licence Number CKV 659 Prov. MB NSC # MB9000790 Odometer Reading 749747 Odom. Type km mi

Vehicle Identification Number 3HSD2T2R1PN114339 Make IHC Model LT65 Year 23 Unit # 324

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any) P-1(a) Engine Shut Down

Section 2 Suspension: Defects (if any)

Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 3H-15(b) Drum Brake System

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	19.3	19.3	420.5	420.9		
2	21.1	19.4	420.1	419.8		
3	21.0	19.4	420.6	420.3		
4						
5						
Final Measurement						

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any)

Section 7 - Electrical System: Defects (if any) 7-1(a) Wiring 7-3(b) Trailer Cord

Section 8 - Body: Defects (if any) 8-12(a) Bumper 8-13(a) Windshield

Section 9 - Tire & Wheel: Defects (if any)

Axle	Tread Depth						Air Pressure					
	Initial		Corrected		Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R	L	R	L	R
1	12	12			100	100			100	100		
2	11	16	13	14			100	100	100	100		
3	10	10	10	13			100	100	100	100		
4												
5												

Section 10 - Coupling Devices: Defects (if any) 10-7(h) R.F.H. Coupler

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date: