



ABILENE, TX	ALBUQUERQUE, NM	BRYAN, TX	CALVERT CITY, KY
EL DORADO, AR	FARMINGTON, MO	FARMINGTON, NM	JACKSON, MO
JACKSON, TN	JONESBORO, AR	MEMPHIS, TN	PARIS, TX
POPLAR BLUFF, MO	SAN ANGELO, TX	SHREVEPORT, LA	SIKESTON, MO
SPRINGFIELD, MO	TEMPLE, TX	TEXARKANA, TX	TUPELO, MS
TYLER, TX	WACO, TX	WEST MEMPHIS, AR	WICHITA FALLS, TX

TAG Truck Center of Jackson

3655 RIDGECREST RD EXT JACKSON, TN 38305

P: (731) 423-3782 Dealer Code: AWHB

#01

SERVICE INVOICE: R620078102:01

ESTIMATE: E620034256

TAG NUMBER: 2645

LICENSE PLATE NUMBER:

BILL TO

XLNT TRANSPORT INC - 2061367

450 WARREN LN

HURRICANE MILLS TN 37078

P: (815) 541-6176

DELIVER TO

XLNT TRANSPORT INC - 2061367

450 WARREN LN

HURRICANE MILLS TN 37078

P: (815) 541-6176

Customer Phone: (815) 541-6176

DATE ARRIVED		DATE INVOICE		SALES TYPE		ADVISOR		TERMS		CUSTOMER PO#	
12/12/2025 9:20:08AM		1/23/2026		SCC		RICHARD G		COD			
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #		ENGINE HOURS	IN SERVICE	ENGINE SERIAL #	ODOMETER		
2025	FORD	Truck	1FDZS96M5WVA17061	01					203,196		

Operations

JOB# 1 CLUTCH TRANSMISSION COMPLAINT

NEW TRANSMISSION

CUSTOMER PAY

CLAIM NUMBER#

COMPLAINT: *CLUTCH COMPLAINT **

MAY HAVE BAD CLUTCH, MAKING GRINDING NOISE AND GEAR STOPS WHEN CLUTCH IS PRESSED IN

CAUSE:

CORRECTION: TL - UNIT WILL NEED FURTHER INSPECTION OF CLUTCH IN REMOVAL, ADDING CLUTCH TO ESTIMATE pulled unit into the shop and removed clutch inspection plate and didnt see any obvious damage to the clutch. i noticed the pto had been leaking so i drained the trans fluid and didnt find any metal on the drain plug and fluid looked to be okay. so i started to removed the transmission and started with the crossmember from fuel tank to fuel tank and it took right at 1 hour just to remove it bc one of the bolts was cross threaded and rusty. i then removed the air lines from the pto pump and drained fluid from the pto i removed pto pump and got it out of the way and the removed the pto. once the pto was off i found metal in the bottom of the pto and found 1 broken tooth on the pto and also found gear damage inside the transmission.

STATUS	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
SOLD	1	620X/RTLOF16713AWEL	FUL,RTLOF16713A	4,841.32	4,841.32
SOLD	1	620X/RTLOF16713AWEL-CORE	FUL,RTLOF16713A CORE	2,891.46	2,891.46
SOLD	1	620X/489XLAHX A3XKWEL	PTO	1,379.08	1,379.08
SOLD	1	620X/PAN SYN 50W	50W SYN TRANS FLUID (5 GL.)	120.71	120.71
SOLD	1	620V/SP 127760	BRAKE-CLUTCH BRAKE DISC ASSEMB	31.03	31.03
SOLD	1	620V/FUL K2262	SEAL - REAR BEARING COVER, MAI	27.90	27.90
SOLD	12	620V/PIC 4620	*NON-CHLOR BRAKE CLNR	2.94	35.28
SOLD	-1	WARR	DEDUCTIBLE	2,150.00	-2,150.00
SOLD	-1	620X/RTLOF16713AWEL-CORE	FUL,RTLOF16713A CORE	2,891.46	-2,891.46
SOLD		LABOR			1,092.00

TAG Truck Center of Jackson

3655 RIDGECREST RD EXT JACKSON, TN 38305

P: (731) 423-3782 Dealer Code: AWHB

Page 2 of 4

SERVICE INVOICE: R620078102:01**ESTIMATE: E620034256**

SOLD	Prepay: 0.00	Parts: 6,435.32	Labor: 1,092.00	Misc: -2,150.00	Sublet: 0.00	Subtotal:
						5,377.32

Job # Subtotal: 5,377.32

JOB# 2 INSTALL DRIVELINE AND/OR CHECK DRIVELINE**CUSTOMER PAY**

CLAIM NUMBER#

COMPLAINT: INSTALL DRIVELINE AND JUMPSTART

CAUSE:

CORRECTION: installed driveshaft

STATUS	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
SOLD		LABOR			52.00

SOLD	Prepay: 0.00	Parts: 0.00	Labor: 52.00	Misc: 0.00	Sublet: 0.00	Subtotal: 52.00
------	--------------	-------------	--------------	------------	--------------	-----------------

Job # Subtotal: 52.00

JOB# 3 OTHER TRANSMISSION COMPLAINT**CUSTOMER PAY**

CLAIM NUMBER#

COMPLAINT: TRANSMISSION COMPLAINT

CAUSE:

CORRECTION: installed pto and pto pump installed clutch inspection cover and installed brace from fuel tank to fuel tank with new nuts and bolts. no fluid in transmission it is empty. caged brake chambers and towed unit into the shop. removed brace from tank to tank, removed clutch inspection cover, removed drive shaft, removed pto pump, removed pto. removed clutch linkage removed trans cooler lines. removed temp sensor and disconnected all electrical connections. disconnected air lines and removed shift tower. removed bell housing bolts and removed transmission. removed clutch fork and bell housing from old trans, and inspected new pto and verified the right pto. cleaned off gasket from bell housing and installed bell housing to the new transmission with new gasket. installed new clutch brake and installed the clutch fork. removed cooler line fittings from old trans installed them to the new trans, removed sensors from old trans installed to new trans removed yoke, output shaft seal and housing from old trans installed to the new trans with new seal and gasket. installed transmission with all bell housing bolts. installed trans cooler lines installed shift tower with new gasket. plugged in all electrical connections/sensors. installed clutch linkage. installed new pto with proper shims and checked backlash. installed pto pump installed drive shaft and filled transmission with fluid. removed cage bolts from brake chamber. will test drive unit in the morning. new transmission serial number 1658048 old transmission serial number 1636235 new PTO serial number 25454352

STATUS	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
SOLD		LABOR			3,330.00

SOLD	Prepay: 0.00	Parts: 0.00	Labor: 3,330.00	Misc: 0.00	Sublet: 0.00	Subtotal:
						3,330.00

Job # Subtotal: 3,330.00

TAG Truck Center of Jackson

3655 RIDGECREST RD EXT JACKSON, TN 38305

P: (731) 423-3782 Dealer Code: AWHD

Page 3 of 4

SERVICE INVOICE: R620078102:01**ESTIMATE: E620034256****JOB# 4 CHASSIS COMPLAINT****CUSTOMER PAY**

CLAIM NUMBER#

COMPLAINT: WHEEL SEAL LEAKING

CAUSE:

CORRECTION: CUSTOMER DOING REPAIRS HIMSELF

STATUS	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
SOLD		LABOR			0.00

SOLD Prepay: 0.00 Parts: 0.00 Labor: 0.00 Misc: 0.00 Sublet: 0.00 Subtotal: 0.00

Job # Subtotal: 0.00

JOB# 5 MISC LABOR**WARRANTY**

CLAIM NUMBER#

COMPLAINT: WELLER POLICY HALF OF TRANSMISSION PART ONLY AT PRICE OF \$2150.00 PER RICH 615-264-2750

CAUSE:

CORRECTION: new transmission serial number 1658048 old transmission serial number 1636235 new PTO serial number 25454352

STATUS	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
SOLD	1	WARR	DEDUCTIBLE		
SOLD		LABOR			

SOLD Prepay: 0.00 Parts: 0.00 Labor: 0.00 Misc: 0.00 Sublet: 0.00 Subtotal: 0.00

Job # Subtotal: 0.00