

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 10-16-2025 Serial# GJD00264
Make: cat Location: R/C
Model: 313F Hours/Mileage: 1,383

Work Performed (print)

Installed new bucket cylinder rod and
pinned to bucket

Parts/supplies used

- A.
- B. 1-30R-1528 rod
- C. 2-235-7679 seal's
- D. 1-2487857 bearing
- E. 4-6v-0357 o'ring
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert , Danyel Willingham

Toatal hours spent on Repairs: 4 1/2

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 10/10/2025 Serial# GJD00264
Make: cat Location: R/C
Model: 313f Hours/Mileage: 1,383

Work Performed (print)

Hyd leak found bucket cylinder leaking. removed
rod to take to dynamic power to have seal kit
installed found rod scratched will need repaired
by dynamic power if they can if not new rod will
be needed

Parts/supplies used

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert,Danyel Willingham

Toatal hours spent on Repairs: 6 1/2

In Service(Y/N) no

Repairs Complete (Y/N) no

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

Date begin 9/4/2025 Serial# GJD00264

Make: cat Location: R/C

Model: 313F Hours/Mileage: 1,373

Work Performed(print)

Removed pin's put thub back into storge
postion for digging test holes

Parts/supplies used (print):

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):

Robert,Danyel Willingham

Toatal hours spent on Repairs: 1

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -

Explain:

MECHANIC EQUIPMENT REPAIR REPORT

Date begin 9/3/2025 Serial# GJD00264

Make: cat Location: R/C

Model: 313f Hours/Mileage: 1,373

Work Performed(print)

Removed and installed valve, removed bucket
and installed digging bucket and removed pin's to
lower thumb

Parts/supplies used (print):

- A. 1-504-8890 valve
- B. 1-618-3006 gasket
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):

Robert, Danyel Willingham

Toatal hours spent on Repairs: 5 1/2

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -

Explain:

MECHANIC EQUIPMENT REPAIR REPORT

Date begin 8/27/2025 Serial# GJD00264

Make: cat Location: R/C

Model: 313F Hours/Mileage: 1,373

Work Performed(print)

trouble shoot engine codes with computer found
engine intake throttle valve not responding ordered
part's

Parts/supplies used (print):

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 3

In Service(Y/N) yes

Repairs Complete (Y/N) no

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

Date begin 8/26/2025

Serial# GJD00264

Make: cat

Location: R/C

Model: 313F

Hours/Mileage: 1,373

Work Performed(print)

Trouble shoot engine fault code

Parts/supplies used (print):

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):

Robert Willingham

Toatal hours spent on Repairs: 4

In Service(Y/N) yes

Repairs Complete (Y/N) no

If No -

Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 6/25/2024

Serial: GJD00264

Make: cat

location: R/C

Model: 313 F

Hours/Mileage: 1,277

Work performrd (print)

installed liner around raidator and
cleared codes on engine for throttle
actuator

Parts/supplies used (print)

A: 1-451-7739 liner

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 3/6/2024

Serial: GJD00264

Make: cat

location: R/C

Model: 313F

Hours/Mileage: 1,221

Work performrd (print)

Repaired wiring harness due to
a stick that popped up thru a hole
on guard from the track's

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 8/10/2023

Serial: GJD00264

Make: cat

location: 105

Model: 313 F

Hours/Mileage: 1,174

Work performrd (print)

Installed longer bolt's to put
thumb in storage

Parts/supplies used (print)

A: 2- bolt's

B: 2-nut's

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham

Total Hours spent on Repair: 1

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 8/3/2023

Serial: GJD00264

Make: cat

location: 105

Model: 313 F

Hours/Mileage: 1,174

Work performrd (print)

Put thumb into storage

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham

Total Hours spent on Repair: 1

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 7/28/2023

Serial: GJD00264

Make: Cat

location: 105

Model: 313 F

Hours/Mileage: 1,174

Work performrd (print)

Pressed in new bearings and seal
and installed new pin's

Parts/supplies used (print)

A: 2-086-0523 pin's

B: 2-096-4876 nut's

C: 2-099-0724 bolt's

D: 4-367-8465 o'rings

E: 2-229-1091 bushing's

F: 2-248-7836 seal's

Repaired Completed By (Mechanic-Print)

Robert willingham,Jared Willingham

Total Hours spent on Repair: 5

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 6/29/2023

Serial: GJD00264

Make: cat

location: Farm

Model: 313 F

Hours/Mileage: 1,136

Work performrd (print)

Took thumb out of storage and
jumped started tractor

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham, Jared Willingham

Total Hours spent on Repair: 1

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 5/30/2023

Serial: GJD00264

Make: Cat

location: 3514

Model: 313F

Hours/Mileage: 1,113

Work performrd (print)

Removed clean out bucket and
installed digging bucket

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert willingham,Danyel Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 3/22/2023

Serial: GJD00264

Make: Cat

location: 3514

Model: 313

Hours/Mileage: 1,000

Work performrd (print)

Did 1000 hour service

Parts/supplies used (print)

A: 1-428-7984 air filter

B: 1-360-8960 fuel filter

C: 1-311-3901 fuel water/sep filter

D: 1-558-0428 oil filter

E: 1-372-9328 cab-n-air filter

F: 1-293-1183 A/C filter

Repaired Completed By (Mechanic-Print)

Justin Garoufalias

Total Hours spent on Repair: 4

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 1/19/2023

Serial: GJD00264

Make: cat

location: R/C

Model: 313

Hours/Mileage: 983

Work performrd (print)

Removed front window, cut old
glass out and installed new glass

Parts/supplies used (print)

A: 1-156-6472 front glass

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham, Justin Garoufalias

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 12/8/2022

Serial: GJD00264

Make: Cat

location: 3514

Model: 313

Hours/Mileage: 975

Work performrd (print)

Changed out bucket

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 10/12/2022

Serial: GJD00264

Make: cat

location: 3514

Model: 313

Hours/Mileage: 910

Work performrd (print)

Replaced keeper bolt on
thumb

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 9/29/2022

Serial: GJD00264

Make: cat

location: 3514

Model: 313

Hours/Mileage: 872

Work performrd (print)

Loaded bucket and took to 3514
and removed clean out bucket
and installed dig bucket, and serviced
fan for the fire's

Parts/supplies used (print)

A: 1-42323 air filter

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Justin Garoufalias

Total Hours spent on Repair: 6

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 5/20/2022

Serial: GJD00264

Make: cat

location: R/C

Model: 313

Hours/Mileage: 857

Work performrd (print)

Set up thumb for opp

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Justin Garoufalias

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 5/11/2022

Serial: GJD00264

Make: cat

location: R/C

Model: 313

Hours/Mileage: 857

Work performrd (print)

Changed out buckets

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham , Justin garoufalias

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 7/12/2021

Serial: GJD00264

Make: cat

location: R/C

Model: 313 F

Hours/Mileage:

755

Work performrd (print)

Welded on Bucket thub on machine

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Justin Garoufalias

Total Hours spent on Repair:

8

In Service (y/n) no

Repairs complete (y/n) no

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 7/10/2021

Serial: GJD00264

Make: cat

location: R/c

Model: 313 F

Hours/Mileage:

755

Work performrd (print)

Installment on bucket thumb attachment

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

welder, crane

Total Hours spent on Repair:

6

In Service (y/n) no

Repairs complete (y/n) no

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 4/7/2021

Serial: GJD00264

Make: Cat

location: R/C

Model: 313

Hours/Mileage: 755

Work performrd (print)

welding on bucket

Parts/supplies used (print)

A: welding machine

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Justin Garoufalias

Total Hours spent on Repair: 7

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 4/6/2021

Serial: GJD00264

Make: Cat

location: R/C

Model: 313

Hours/Mileage: 755

Work performrd (print)

Welding Bucket

Parts/supplies used (print)

A: welder

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Justin Garoufalias

Total Hours spent on Repair: 8

In Service (y/n) no

Repairs complete (y/n) no

If No Explain:

still welding bucket