04131338

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outle
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL

Manitoba

C114086

Date Inspection Started: 15 DAY / 07 MO. / 26 YR.
Date Inspection Completed: 15 DAY / 07 MO. / 26 YR.
Inspection Expiry Date: 31 DAY / 07 MO. / 27 YR.

Station Number: A5952 — Station Name: KMMJ LTD — City: Virden
Mechanic Number: M02018 — Mechanic Signature: Matt Ltd — Station Phone Number: 2045512038

Vehicle Owner: 5214765 Manitoba Ltd
Address: Box 441 — City: Souris — Province: MB — Postal Code: R0K2C0 — Phone:

[X] Pass/Safe Vehicle
[ ] Fail/Unsafe Vehicle
[ ] Fail/Hazardous

Licence Number: TF6055 — Prov.: MB — NSC #: 0997627 — Odometer Reading: — Odom. Type: [ ] km [ ] mi

Vehicle Identification Number: 2DEALBE37W4042751 — Make: Doepker — Model: Hopper — Year: 22 — Unit #:

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck (GVWR) KGS ____Truck Tractor ____Trailer __X__Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) — Defects (if any) — Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any) RH ID marker light broken replace
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining IN		Drum/Rotor IN		Stroke FW	
Axle	L	R	L	R	L	R
1	.070	.070	16.54	16.54	IN	IN
2	.60	.070	16.54	16.55	IN	IN
3	.050	.050	16.54	16.55	IN	IN
4						
5						
	Final Measurement					

	Tread Depth								Air Pressure							
	Initial 32nds				Corrected				Initial PSI				Corrected			
Axle	L		R		L		R		L		R		L		R	
1	17	17	15	15					100	100	100	100				
2	5	5	15	15					100	100	100	100				
3	14	13	9	9					100	100	100	100				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE