04063733

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outl
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL

Manitoba

C055828

Date Inspection Started: DAY 31 MO. 03 YR. 26

Date Inspection Completed: DAY 01 MO. 04 YR. 26

Inspection Expiry Date: DAY 30 MO. 04 YR. 27

Station Number: A53611 Station Name: Inland City: Brandon

Mechanic Number: M81903 Mechanic Signature: Dwayne Vorta Station Phone Number: 204-728-6681

Vehicle Owner: Kurtenbach Trucking

Address: City: Province: Postal Code: Phone:

- [X] Pass/Safe Vehicle
- [X] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: T F6099 Prov.: MB NSC #: Odometer Reading: — Odom. Type: [ ] km [ ] mi

Vehicle Identification Number: 2LDA#30225V077758 Make: Lode King Model: Grain Year: 2025 Unit #:

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR KGS ____Truck Tractor ____Trailer X Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X		Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) 6-1-X: Left outer rear light half LEDS inop
X		Section 7 - Electrical System: Defects (if any)
X	X	Section 8 - Body: Defects (if any) 8-5-X: Broken rivet by right 1st axle front of fender mount.
X		Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any)

Brake Inspection Type: A B (C) D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining IN L	Lining IN R	Drum/Rotor L	Drum/Rotor R	Stroke IN L	Stroke IN R
1	3/4	3/4			1.5	1.5
2	3/4	3/4			1.5	1.5
3						
4						
5						
	Final Measurement					

Axle	Tread Depth 32nds Initial L		Initial R		Corrected L		Corrected R		Air Pressure psi Initial L	Initial R			Corrected L		Corrected R	
1	12	11	11	11					120	124	90	89		120	120	120
2	17	17	14	13					101	100	100	117	120	120	120	120
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE