04063734

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Out
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL

Manitoba

C055827

Date Inspection Started: DAY 31 MO. 03 YR. 26

Date Inspection Completed: DAY 01 MO. 04 YR. 26

Inspection Expiry Date: DAY 30 MO. 04 YR. 27

Station Number: A53161 Station Name: Inland City: Brandon

Mechanic Number: M18103 Mechanic Signature: [signature] Station Phone Number: 204-728-6681

Vehicle Owner: Kurtenbach Trucking

Address: City: Province: Postal Code: Phone:

- [X] Pass/Safe Vehicle
- [X] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: TF60198 Prov.: MB NSC #: Odometer Reading: — Odom. Type: km mi

Vehicle Identification Number: 2LDAH2831SV077757 Make: Lode King Model: Grain Year: 2025 Unit #:

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR ____ KGS ___Truck Tractor ___Trailer X Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any) 6-1-X: 3 rear red clearance lights inop.
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X	X	**Section 9 - Tire & Wheel:** Defects (if any) 9-4-X: adjust tire pressure.
X	X	**Section 10 - Coupling Devices:** Defects (if any) 10-7-X: 5th wheel pins & bushings.

Brake Inspection Type: A B (C) D E Circle appropriate Letter for Internal Brake Component Inspection

	Lining IN		Drum/Rotor		Stroke IN	
Axle	L	R	L	R	L	R
1	3/4	3/4			1.5	1.5
2	3/4	3/4			1.5	1.5
3	3/4	3/4			1.5	1.5
4						
5						
	Final Measurement					

Tread Depth 32nds

	Initial				Corrected			
Axle	L		R		L		R	
1	12	11	17	17				
2	11	12	8	7				
3	8	8	14	16				
4								
5								

Air Pressure PSI

	Initial				Corrected			
	L		R		L		R	
1	105	107	114	117	120	120	120	120
2	117	117	98	88	120	120	120	120
3	107	105	120	118	120	120		120
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE