04144049

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outle
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL
Manitoba
C141057

Date Inspection Started: 02 (DAY) 10 (MO.) 26 (YR.)
Date Inspection Completed: 02 (DAY) 10 (MO.) 26 (YR.)
Inspection Expiry Date: 31 (DAY) 10 (MO.) 27 (YR.)

Station Number: A5195 1 — Station Name: KMMJ CTD — City: Vicki
Mechanic Number: M012108 — Mechanic Signature — Station Phone Number: 204 857 2038

Vehicle Owner: 5274165 MB LHI
Address: Box 441 — City: Sowis — Province: MB — Postal Code: R0K2C0 — Phone

- [X] Pass/Safe Vehicle
- [ ] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: CKC4210 — Prov.: MB — NSC #: 0997627 — Odometer Reading: 765265 — Odom. Type: [X] km [ ] mi

Vehicle Identification Number: 1BPGSIM87414 — Make: KW — Model: U900 — Year: 18 — Unit #:

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck — GVWR 24,500 KGS — _X_Truck Tractor — ____Trailer — ____Semi-Trailer — ____Bus — ____School Bus — ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X	X	**Section 6 - Lamps:** Defects (if any) RF #3) marker light out, replace
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining IW		Drum/Rotor IW		Stroke IW	
Axle	L	R	L	R	L	R
1	.25	.25	1.61	1.61		
2	.70	.70	16.52	16.52	JIR	JIR
3	.70	.70	16.52	16.52	JIR	JIR
4						
5						
	Final Measurement					

	Tread Depth								Air Pressure							
	Initial 32nds				Corrected				Initial PSI				Corrected			
Axle	L		R		L		R		L		R		L		R	
1		16	16							100	100					
2	18	18	18	19					100	100	100	100				
3	21	19	21	21					100	100	100	100				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature — Date: _____

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE