04144056

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL

Manitoba
C141064

Date Inspection Started: 06 (DAY) 10 (MO.) 26 (YR.)
Date Inspection Completed: 06 (DAY) 10 (MO.) 26 (YR.)
Inspection Expiry Date: 31 (DAY) 10 (MO.) 27 (YR.)

Station Number: A5 19 5 1 — Station Name: KMMJ LTD — City: Vita
Mechanic Number: M 10 2 10 8 — Mechanic Signature: MK 2bL — Station Phone Number: 2048512038

Vehicle Owner: 5214165 MB Ltd
Address: Box 442 — City: Sanis — Province: MB — Postal Code: R04 2C0 — Phone:

- [X] Pass/Safe Vehicle
- [ ] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: TG 139167 — Prov.: MB — NSC #: 097627 — Odometer Reading: — Odom. Type: [ ] km [ ] mi

Vehicle Identification Number: 1M1K52922NW613779 — Make: Wilson — Model: Dak — Year: 22 — Unit #: Land.

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR KGS ____Truck Tractor ____Trailer X Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) — Defects (if any) — Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining IN		Drum/Rotor IN		Stroke IN	
Axle	L	R	L	R	L	R
1	.75	.75	16.52	16.52	1 1/2	1 1/2
2	.75	.75	16.52	16.52	1 1/2	1 1/2
3	.75	.75	16.52	16.52	1 1/2	1 1/2
4						
5						
	Final Measurement					

	Tread Depth Initial 32nds				Tread Depth Corrected				Air Pressure Initial PSI				Air Pressure Corrected			
Axle	L		R		L		R		L		R		L		R	
1	10	10	13	9					100	100	100	100				
2	16	16	15	15					100	100	100	100				
3	6	15	5	5					100	100	100	110				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature — Date: _____

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE