04144057

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL
Manitoba
C141065

Date Inspection Started: DAY 06 MO. 10 YR. 26
Date Inspection Completed: DAY 06 MO. 10 YR. 26
Inspection Expiry Date: DAY 27 MO. 10 YR. 27

Station Number: A59517 Station Name: KMMT LTD City: Virden
Mechanic Number: M02108 Mechanic Signature: [signature] Station Phone Number: 204 851 2035

Vehicle Owner: 5214165 MB Ltd
Address: Box 447 City: Sanna Province: MB Postal Code: R0K2C0 Phone:

[X] Pass/Safe Vehicle
[ ] Fail/Unsafe Vehicle
[ ] Fail/Hazardous

Licence Number: TG39612 Prov.: MB NSC #: 0997627 Odometer Reading: Odom. Type [ ] km [ ] mi
Vehicle Identification Number: 1W1K53123XW663731 Make: Wilson Model: deck Year: 22 Unit #: P.P.
[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR KGS ____Truck Tractor ____Trailer X Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	.75	.75	16.52	16.52	1/2	1/2
2	.75	.75	16.52	16.52	1/2	1/2
3						
4						
5						
	Final Measurement					

	Tread Depth								Air Pressure							
	Initial 32nds				Corrected				Initial 95#				Corrected			
Axle	L		R		L		R		L		R		L		R	
1	11	11	13	13					100	100	100	100				
2	16	16	9	9					100	100	100	100				
3																
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE