

03896523

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATEManitoba Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920Manitoba 

A881931

Date Inspection Started
DAY MO. YR.
04 12 24Date Inspection Completed
DAY MO. YR.
04 12 24Inspection Expiry Date
DAY MO. YR.
31 12 25Station Number
A5302Station Name
Virden Truck & TrailerCity
VirdenMechanic Number
101146Mechanic Signature
[Signature]Station Phone Number
204 748-1887Vehicle Owner
Cyanide Acres Ltd.

Box 1000

Virden

MB

R1M 2C0

Address

City

Province

Postal Code

Phone

☒ Pass/Safe Vehicle☐ Fail/Unsafe Vehicle☐ Fail/Hazardous

Licence Number

K2D977

Prov.

MB

NSC #

MB9173997

Odometer Reading

654179

Odom. Type

☒ km☐ mi

Vehicle Identification Number

1M1AN07YX0A010730

Make

MACK

Model

CH440

Year

12

Unit #

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any)

Section 2 Suspension: Defects (if any)

Section 3 - Brake Systems: 3H 3A

Defects (if any) Circle Brake Type

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Lining Drum/Rotor Stroke

Axle L R L R L R

1 67 67 16.5 16.5 1 1

2 60 60 16.5 16.5 1.25 1.25

3 60 60 16.5 16.5 1.25 1.25

4

5

Final Measurement

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any)

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any)

Section 9 - Tire & Wheel: Defects (if any)

Tread Depth Air Pressure

Initial Corrected Initial Corrected

Axle L R L R L R L R

1 17 16 100 100

2 18 17 15 18 100 100 100 100

3 18 15 15 16 100 100 100 100

4

5

Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not