

03935159

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATEManitoba Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920Manitoba 

A932002

Date Inspection Started DAY: 11 MO: 03 YR: 215	Station Number A1301117	Station Name Lucky Star Wash & Seal	City Winnipeg
Date Inspection Completed DAY: 113 MO: 03 YR: 215	Mechanic Number M10121210	Mechanic Signature Kerry Brown	Station Phone Number 204-571-1531
Inspection Expiry Date DAY: 311 MO: 03 YR: 216	Vehicle Owner Doublediamond Farm Supply Company LTD Box 776 Hwy #10 South Boissevain MB R0H0E0		
Address		City	Province
		Postal Code	Phone

☒ Pass/Safe Vehicle	Licence Number T1190013	Prov. MB	NSC # N/A	Odometer Reading N/A	Odom. Type km ☐ mi ☐
☒ Fail/Unsafe Vehicle	Vehicle Identification Number 2A1E1A1851N143R101011819	Make N/A	Model Tanker	Year 1988	Unit # SL10
☐ Fail/Hazardous	☒ Confirmed legible Vehicle Identification Number on vehicle				

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

 Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
X		Section 2 Suspension: Defects (if any)																																																																							
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type X-15C-L3+R3 brake shoe lining thickness less than 5/16" X-14B R2 Park brake applying broken Section 4 - Steering: Defects (if any)																																																																							
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X	X	Section 6 - Lamps: Defects (if any) X-1L - license plate lamp inoperative X-3C-LHS/RHS Tank reflective tape peeling Section 7 - Electrical System: Defects (if any)																																																																							
X		Section 8 - Body: Defects (if any)																																																																							
X		Section 9 - Tire & Wheel: Defects (if any)																																																																							
X		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>16</td> <td>16</td> <td>16</td> <td>16</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>15</td> <td>14</td> <td>13</td> <td>16</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>13</td> <td>13</td> <td>16</td> <td>14</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td colspan="4">22"</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table> Section 10 - Coupling Devices: Defects (if any)	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	16	16	16	16	100	100	100	100	2	15	14	13	16	100	100	100	100	3	13	13	16	14	100	100	100	100	4	22"								5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	16	16	16	16	100	100	100	100																																																																	
2	15	14	13	16	100	100	100	100																																																																	
3	13	13	16	14	100	100	100	100																																																																	
4	22"																																																																								
5																																																																									

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.