

Experian AutoCheck Report

Report run: 07/09/2026 16:18:38 EDT

2013 Chevrolet Silverado 1500 Work Truck

Regular Cab 2D (4.3L V6 SMPI Gasoline)

VIN:	1GCNCPEX7DZ211645
Class:	Pickup - Fullsize
Country of Assembly:	United States
Vehicle Age:	13 year(s)
Estimated In Service:	11/29/2012
Last Reported Odometer:	38,579 (04/22/2025)

One Owner
AutoCheck
Vehicle Usage
 Lease



AutoCheck Score

Similar vehicles usually range between 69 and 84

Vehicle History at a Glance

<p>State Title Brand</p> <p>CLEAN</p>	<p>Auction Brand / Issues Odometer Problem</p> <p>AUCTION ISSUE REPORTED</p>	<p>Accident / Damage</p> <p>MINOR</p>
<p>Open Recall Check</p> <p>1 OPEN RECALL(S)</p>	<p>Insurance Loss / Transfer</p> <p>NO ISSUE</p>	<p>Odometer Check Last reported odometer: 38,579 (04/22/2025)</p> <p>ODOMETER ISSUE REPORTED</p>
<p>Certified Pre-Owned</p> <p>NO CPO INFO AVAILABLE</p>	<p>Service / Repair</p> <p>NO ISSUE</p>	<p>Additional History</p> <p>NO ISSUES REPORTED</p>



This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)



Accident & Damage

Point of Impact Not Available

- Airbag Deployed
- Structural Damage
- Overturned
- Minor

Damage Date	Damage Type	Severity
08/01/2019	Collision	Minor

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

Open Recall Check

Information Reported: AutoCheck found 1 open recall(s).
 It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 02/05/2021

Recall Type - Safety

NHTSA / OEM Recall No. - 21V053 / N212328790

Campaign Description - Safety: FRONT PASSENGER AIRBAG TAKATA INFLATOR - PRIORITY GROUP 9
 Status: Remedy Available

[More information](#) including remedy or risk factors. Locate your nearest authorized [Chevrolet Dealer](#) to schedule repair.

Recommended Maintenance

OEM Recommended Maintenance Schedule

Based on your vehicle's last reported mileage, these are the most recent and upcoming recommended maintenance intervals from your vehicle's manufacturer.

OEM Recommended Services



37500 Mile Service

- Change engine oil and filter
- Check accelerator pedal
- Check automatic transmission shift lock control function



45000 Mile Service Not Yet Due

- Change engine oil and filter
- Check accelerator pedal
- Check automatic transmission shift lock control function



52500 Mile Service Not Yet Due

- Change engine oil and filter
- Check accelerator pedal
- Check automatic transmission shift lock control function

Odometer Check

Problem Reported
 One or more odometer problems have been reported to AutoCheck by the state Division of Motor Vehicles (DMV) or auction sources OR there is a potential odometer discrepancy when AutoCheck examined the sequence of reported odometer readings.



State Title Odometer Check

No issues reported



Auction Odometer Check

The following odometer brand(s) has been announced by an auction:

Not Actual Miles



Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2013 Chevrolet Silverado 1500 Work Truck (1GCNCPEX7DZ211645) Report Run Date: 07/09/2026 16:18:38 EDT

2012

Vehicle Prep and Other Pre-Titling Events

Location: LA

Preparation Date: 11/2012

Event Date	Location	Odometer	Data Source	Details
11/29/2012	LA	40	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection

2012

Owner 1

Location: LA

Owned From: 12/2012

Usage: Lease

Event Date	Location	Odometer	Data Source	Details
12/06/2012	BATON ROUGE, LA		Motor Vehicle Dept.	Title
12/06/2012	LA		Motor Vehicle Dept.	Title(Title #:B4178385)
12/06/2012	BATON ROUGE, LA		Motor Vehicle Dept.	Registration Event/Renewal
11/04/2013	LA	1,171	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
11/06/2014	LA	2,558	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
11/19/2015	LA	4,113	Motor Vehicle Dept.	Failed Emission Inspection Passed Safety Inspection
11/30/2015	LA	4,163	Motor Vehicle Dept.	Failed Emission Inspection Passed Safety Inspection
12/02/2015	LA	4,239	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
09/22/2016	LA		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
12/27/2016	LA	6,555	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
01/23/2018	LA	10,812	Motor Vehicle Dept.	Passed Emission Inspection Safety Inspection
01/07/2019	LA	15,562	Motor Vehicle Dept.	Failed Emission Inspection Passed Safety Inspection
01/25/2019	LA	15,627	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
08/01/2019	BATON ROUGE, LA	180,007 †	Damage Report	Accident or Damage Reported Minor Damage Reported
09/08/2020	LA		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)













Event Date	Location	Odometer	Data Source	Details
02/05/2021			Manufacturer	Manufacturer Recall NHTSA Recall 21V053 / Mfr. Recall N212328790 Safety: FRONT PASSENGER AIRBAG TAKATA INFLATOR - PRIORITY GROUP 9 LOCATE YOUR NEAREST AUTHORIZED CHEVROLET DEALER TO SCHEDULE REPAIR. Status: Remedy Available
04/22/2025	SOUTHWEST REGION	38,579	Auto Auction	Reported at Auto Auction
04/25/2025	SOUTHWEST REGION		Auto Auction	Auction Announced as Not Actual Miles



† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

Warranty Check

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic 	-	-		36 months / 36000 miles
Battery 	-	-	-	Contact a certified dealer to verify coverage
Corrosion 	57,772	-		72 months / 100000 miles
Powertrain 	57,772	-		60 months / 100000 miles
Roadside Assistance 	57,772	-		60 months / 100000 miles
Safety Restraint 	-	-	-	Contact a certified dealer to verify coverage

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1GCNCPEX7DZ211645) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterm or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.